

FAE - Issues #178

Ubuntu

11/17/2022 11:27 AM -

Status:	Feedback	Start date:	11/17/2022
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LKD3588 Linux SDK 1.0	Name:	
Component_fae:		Tel.:	
Probability:	High	:	
Seriousness:		:	
Problem Type:		EMMC :	
Description			
1500000115200			
diff --git a/kernel/arch/arm64/boot/dts/rockchip/rk3588-linux.dtsi b/kernel/arch/arm64/boot/dts/rockchip/rk3588-linux.dtsi			
index d8c7c2465..6ad04907b 100644			
--- a/kernel/arch/arm64/boot/dts/rockchip/rk3588-linux.dtsi			
+++ b/kernel/arch/arm64/boot/dts/rockchip/rk3588-linux.dtsi			
@@ -45,7 +45,7 @@ fiq_debugger: fiq-debugger {			
rockchip,wake-irq = <0>;			
/* If enable uart uses irq instead of fiq */			
rockchip,irq-mode-enable = <1>;			
rockchip,baudrate = <1500000>; /* Only 115200 and 1500000 */			
- rockchip,baudrate = <115200>; /* Only 115200 and 1500000 */			
+ rockchip,baudrate = <115200>; /* Only 115200 and 1500000 */			
interrupts = <GIC_SPI 423 IRQ_TYPE_LEVEL_LOW>;			
pinctrl-names = "default";			
pinctrl-0 = <&uart2m0_xfer>;			

History

#1 - 11/17/2022 11:50 AM -

- Tracker changed from Release to Issues
- Status changed from New to Feedback