

LP162 - Bug #279

9V


05/17/2023 06:54 PM - mike

Status:	Closed	Start date:	05/17/2023
Priority:	Immediate	Due date:	05/19/2023
Assignee:	jing	% Done:	0%
Category:	H.W	Estimated time:	48.00 hours
Target version:		Spent time:	5.00 hours
OS:	LP162	OS:	Ubuntu
CPU:	RK3588	Kernel:	Linux LPA3588 5.10.110
Board:	LPB3588	APP:	
Boot mode:	02	Boot mode:	
Boot partition:	01	Boot partition:	
Boot partition:	03	Boot partition:	
Image:	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	EMMC:	

Description

1. LP162 9V
2. F/R 50%

!



!

History

#1 - 05/19/2023 11:24 AM - Anonymous

[update]
LJ160 03 02 9v 3A usb
F/R 100%

#2 - 09/18/2023 10:38 AM -

- Status changed from New to Closed
- changed from LZ160XXX03_FT_DB_BASE_221227A.img to LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img
- changed from Debian to Ubuntu

- changed from 5.10.110 to Linux LPA3588 5.10.110

9v3Ausb

Files

clipboard-202305171853-i6mvz.png	290 KB	05/17/2023	mike
----------------------------------	--------	------------	------