

LP160 - Bug #304

LPA3588_Ubuntu 20.04.5_ BT

05/26/2023 07:39 PM

Status:	Closed	Start date:	05/26/2023
Priority:	Normal	Due date:	
Assignee:	Linx	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
ID:	LP160	OS:	Ubuntu
CPU:	RK3588	Kernel:	Linux LPA3588 5.10.110
Model:		APP:	
Board:	02	Board:	
Board:	01	Board:	
Board:	03	Board:	
Image:	RK3588_UBUNTU_V1_230519.img	EMMC:	

Description

1. hciconfig hci0 up
2. hcitool dev
3.

History

#1 - 06/02/2023 11:30 AM - sun


- Assignee changed from sun to Linx

#2 - 06/02/2023 01:46 PM - Linx

- File clipboard-202306021345-tl6o2.png added

- File clipboard-202306021346-8lu2o.png added

1.



2.

其他设备



65D8K_913F

Dahua 的 MacBook Pro

DESKTOP-VUFAJ0U

LPA3588

#3 - 06/02/2023 04:16 PM - 00

- Status changed from New to Closed

0000ok0000

Files

clipboard-202306021345-tl6o2.png	20.3 KB	06/02/2023	Linx
clipboard-202306021346-8lu2o.png	104 KB	06/02/2023	Linx