

LP162 - Bug #331

A/I INI1 2 3 4 50mV

06/09/2023 06:03 PM -

Status:	New	Start date:	06/09/2023
Priority:	Normal	Due date:	
Assignee:	sun	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LP162	:	Ubuntu
CPU:	RK3588	:	Linux LPA3588 5.10.110,e
:		APP :	
/ :	02	:	
:	01	:	
/ :	03	:	
:	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	EMMC :	

Description

1A/I INI1 2 3 4 1V 7V 14V

2

INI1----cat /sys/devices/platform/fec10000.saradc/iio\:device0/in_voltage4_raw

INI2----cat /sys/devices/platform/fec10000.saradc/iio\:device0/in_voltage2_raw

INI3----cat /sys/devices/platform/fec10000.saradc/iio\:device0/in_voltage6_raw

INI4----cat /sys/devices/platform/fec10000.saradc/iio\:device0/in_voltage7_raw

350mV

1

2INI1,IN2,IN3,IN450mv

50mV

History

- #1 - 09/11/2023 03:31 PM -
- Priority changed from High to Normal

- changed from RK3588_UBUNTU_V1_230519.img to LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img

- changed from Linux LPA3588 5.10.110 to Linux LPA3588 5.10.110,e