

LP112 - Bug #337

□ □ □ □ □ □ □ □ □ □

06/14/2023 11:44 AM - ☐☐

Status:	New	Start date:	06/14/2023
Priority:	High	Due date:	
Assignee:		% Done:	0%
Category:	S.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Item ID:	LZ112	OS:	Ubuntu
CPU:	RK3399Pro	Kernel:	Linux LPA3399Pro 4.4.194
Board:		APP:	
Build type:		Build type:	
Build number:	01	Build number:	
Build date:	01	Build date:	
Build version:	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704	EMMC:	

Description

[illegible]

□ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □

History

#1 - 06/14/2023 01:55 PM -

- Assignee changed from Linx to Anonymous

#2 - 07/03/2023 11:28 AM - ☐☐

```
LZ112000Ubuntu18.0400000003-image/rk3399pro-linux/LZ112/lz112_3399pro_ubuntu18.04_v1.0_20230627_1033
00000000
```

#3 - 07/14/2023 10:33 AM -

```
LZ112 000003-image/rk3399pro-linux/LZ112/lz112_3399pro_ubuntu18.04_v1.0_20230711_2205
00000000(00000000000000000000000000000000)
```

#4 - 07/17/2023 11:32 AM - ☐☐

- File clipboard-202307171132-v6pi3.png added

```
LZ112 \\\192.168.1.250\03-image\rk3399pro-linux\LZ112\lz112_3399pro_ubuntu18.04_v2.01_20230714_1923
```

```

root@LPA3399Pro:~# echo 1 > /sys/class/rfkill/rfkill0/state
root@LPA3399Pro:~# hciconfig
hci0:   Type: Primary  Bus: UART
        BD Address: 34:7D:E4:1D:E3:55  ACL MTU: 1021:8  SCO MTU: 255:12
        DOWN
        RX bytes:4744 acl:0 sco:0 events:100 errors:0
        TX bytes:37444 acl:0 sco:0 commands:2917 errors:0

root@LPA3399Pro:~# echo 1 > /sys/class/rfkill/rfkill0/state
root@LPA3399Pro:~# hciconfig
hci0:   Type: Primary  Bus: UART
        BD Address: 34:7D:E4:1D:E3:55  ACL MTU: 1021:8  SCO MTU: 255:12
        DOWN
        RX bytes:4744 acl:0 sco:0 events:100 errors:0
        TX bytes:42548 acl:0 sco:0 commands:3381 errors:0

root@LPA3399Pro:~# hciconfig hci0 up
[ 380.743541] Bluetooth: hci0 command 0x1003 tx timeout
[ 382.747316] Bluetooth: hci0 command 0x1001 tx timeout

[ 384.751578] Bluetooth: hci0 command 0x1009 tx timeout
Can't init device hci0: Connection timed out (110)
root@LPA3399Pro:~#
root@LPA3399Pro:~# hciconfig
hci0:   Type: Primary  Bus: UART
        BD Address: 34:7D:E4:1D:E3:55  ACL MTU: 1021:8  SCO MTU: 255:12
        DOWN
        RX bytes:4744 acl:0 sco:0 events:100 errors:0
        TX bytes:54692 acl:0 sco:0 commands:4485 errors:0

root@LPA3399Pro:~# █

```

#5 - 07/17/2023 03:13 PM - ☐☐

- ☐☐☐☐☐☐☐ set to 01
- ☐☐/☐☐☐☐☐☐☐ set to 01

#6 - 07/18/2023 04:22 PM - ☐☐

- Priority changed from Urgent to High

Files

clipboard-202307171132-v6pi3.png	46.2 KB	07/17/2023	☐☐
----------------------------------	---------	------------	----