

LP120 - Bug #527

USB2.0 10G

08/27/2024 10:26 AM - EGON

Status:	Closed	Start date:	08/27/2024
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LB120	:	
CPU:	RK3568	:	Linux version 5.10.198 (yangyonghao@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #11 SMP Wed Aug 14 17:46:10 CST 2024
:	LPA3568M8"	APP :	
/ :	04	:	<20%
:	04	:	
/ :	05	:	
:	\\192.168.1.250\01-Public\wilson_test\rk 3568\lpa3568	EMMC :	
Description			
USB 4-5G			

History

#1 - 08/27/2024 01:32 PM - EGON

- changed from 100% to <20%

EGON wrote:

USB2.0 10G 4-5G

#2 - 08/27/2024 05:15 PM - EGON

- Subject changed from USB 10G to USB2.0 10G

SSD USB2.0 SSD 10G 4-5G

#3 - 09/02/2024 01:51 PM - mike

- Status changed from New to Closed