

KP12C - Bug #796

usb2.0 usb3.0 hub 30%

01/14/2025 11:29 AM -

Status:	New	Start date:	01/14/2025
Priority:	Normal	Due date:	
Assignee:	Linx	% Done:	0%
Category:	S.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	KP12C	:	Ubuntu
CPU:	RK3568	:	V5.10.198
:	"LPA3568M4"	APP :	-
/ :	05	:	<50%
:	04	:	RTL8852
/ :	04	:	YT8521SC
:	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img	EMMC :	-
Description			

History

- #1 - 01/14/2025 11:34 AM -
- set to KP12C

- CPU set to RK3568

- set to "LPA3568M4"

- / set to 05

- set to 04

- / set to 04

- set to

\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img

- set to <50%

- set to RTL8852

- set to YT8521SC
- #2 - 01/14/2025 11:54 AM -
- Category changed from Driver to S.W

- Assignee changed from to Linx