



LP201 - Bug #812

D/O 12V

01/21/2025 10:54 AM -

|                 |                                |                 |            |
|-----------------|--------------------------------|-----------------|------------|
| Status:         | New                            | Start date:     | 01/20/2025 |
| Priority:       | High                           | Due date:       |            |
| Assignee:       | shiliang                       | % Done:         | 0%         |
| Category:       | H.W                            | Estimated time: | 0.00 hour  |
| Target version: |                                | Spent time:     | 0.00 hour  |
| :               | LP201                          | :               | Ubuntu     |
| CPU:            | RK3576                         | :               | v6.1.84    |
| :               | LPS3576                        | APP:            | -          |
| /:              | -                              | :               | 100%       |
| :               | -                              | :               | N/S        |
| /:              | 01                             | :               | YT8521SC   |
| :               | ubuntu22.04_lb201_25_01_07.img | EMMC:           | -          |

Description



12.45v  
12.7v

Files

|                                  |        |            |   |
|----------------------------------|--------|------------|---|
| clipboard-202501201455-zpmkw.png | 340 KB | 01/20/2025 | 📄 |
| clipboard-202501211052-vlqbe.png | 486 KB | 01/21/2025 | 📄 |