


LP201 - Bug #813

GPIO55

01/21/2025 03:56 PM

Status:	New	Start date:	01/21/2025
Priority:	High	Due date:	
Assignee:	shiliang	% Done:	0%
Category:	H.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
OS:	LP201	OS:	Ubuntu
CPU:	RK3576	Kernel:	v6.1.84
Board:	LPS3576	APP:	-
Board/Model:	-	Progress:	100%
Board/Model:	-	Board/Model:	N/S
Board/Model:	01	Board/Model:	YT8521SC
Board/Model:	ubuntu22.04_lb201_25_01_07.img	EMMC:	-

Description



```
root@LB3576:/home/neardi/Desktop# ./gpio_test1.sh 54 13 69 19 out 1
54 out 1
13 out 1
69 out 1
19 out 1
root@LB3576:/home/neardi/Desktop# ./gpio_test1.sh 51 7 55 68 in
51 0
7 0
55 0
68 0
root@LB3576:/home/neardi/Desktop# ./gpio_test1.sh 54 13 69 19 out 0
54 out 0
13 out 0
69 out 0
19 out 0
root@LB3576:/home/neardi/Desktop# ./gpio_test1.sh 51 7 55 68 in
51 1
7 1
55 0
68 1
```

Files

clipboard-202501211549-r9crx.png	294 KB	01/21/2025	
clipboard-202501211555-tdtse.png	20.8 KB	01/21/2025	