

LB200 - Bug #837

USB3.0 3.0U

02/17/2025 04:04 PM -

Status:	New	Start date:	02/17/2025
Priority:	Urgent	Due date:	
Assignee:	yuncaï	% Done:	0%
Category:	H.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LB200	:	
CPU:		:	Linux LB3576 6.1.84 #4 SMP Tue Dec 3 11:28:34 CST 2024 aarch64 aarch64 aarch64 GNU/Linux
:		APP :	
/ :		:	
:		:	FD7352S
/ :	02	:	YT8521SC
:	\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	EMMC :	-

Description
USB3.0 3.0HUB HUB 2.0 3.0

HUB 3.0U 2.0
HUB 3.0U 2.0 3.0

V01

History

#1 - 02/18/2025 02:23 PM - yuncaï
- File LB200 V2.0 BUG628 USB V3.0 20250218.doc added

1 C2017 100pF R2012 91K R2015 12K L2001 2.2uH VCC5V0_USB 5.15V 3.5A 4.83V USB 4.8~5.2
2 V01
USB3.0 3 2 USB V2.0 1 USB V3.0 HUB 3

Files

LB200 V2.0 BUG628 USB V3.0 20250218.doc	244 KB	02/18/2025	yuncaï
---	--------	------------	--------