

LP201 - Bug #863

M4

03/04/2025 05:21 PM - mike

|                 |         |                 |            |
|-----------------|---------|-----------------|------------|
| Status:         | New     | Start date:     | 03/04/2025 |
| Priority:       | High    | Due date:       |            |
| Assignee:       |         | % Done:         | 0%         |
| Category:       | M.E     | Estimated time: | 0.00 hour  |
| Target version: |         | Spent time:     | 0.00 hour  |
| OS:             | LP201   | OS:             | Ubuntu     |
| CPU:            | RK3576  | Kernel:         | V6.1.84    |
| GPU:            | LPS3576 | APP:            | -          |
| RAM/Flash:      | -       | Flash:          | 100%       |
| Storage:        | -       | Storage:        | FD7352S    |
| RAM/Flash:      | 01      | Storage:        | YT8521SC   |
| Flash:          | -       | EMMC:           | -          |
| Description     |         |                 |            |