

Issues

#	Project	Tracker	Status	Priority	Subject	OS	File Name	Assignee	Updated
953	LZ201	Bug	New	Urgent	mipi	Ubuntu	rk3576_ubuntu2204_20250429.img		05/19/2025 05:16 PM
952	LZ750	Bug	New	High	thermal dmc cpufreq	Ubuntu	fast boot \\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.1-20250515; kernel:\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.1-20241218\kernel; rootfs:\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.1-20241218\rootfs	sun	05/19/2025 03:25 PM
950	LP162	Bug	New	Normal	TF	Ubuntu	\\192.168.1.250\01-Public\volcan\3588\LPB3588\LPB3588_ubuntu22.04_v1.0_20250415_1639.img	sun	05/15/2025 07:09 PM
949	LP162	Bug	New	Normal	Line pop	Ubuntu	\\192.168.1.250\01-Public\volcan\3588\LPB3588\LPB3588_ubuntu22.04_v1.0_20250415_1639.img	sun	05/15/2025 06:52 PM
948	LP162	Bug	New	Normal	4GB 4.99GB	Ubuntu	\\192.168.1.250\01-Public\volcan\3588\LPB3588\LPB3588_ubuntu22.04_v1.0_20250415_1639.img	sun	05/15/2025 06:51 PM
947	LZ210	Bug	New	High	RK3562J	Ubuntu	rk3562_ubuntu2204_20250409A.img	zenghui	05/14/2025 10:24 AM
946	LP162	Bug	New	High	eth1 MAC	Ubuntu	\\192.168.1.250\01-Public\volcan\3588\LPB3588\LPB3588_ubuntu22.04_v1.0_20250415_1639.img	sun	05/13/2025 03:24 PM
945	LB700	Bug	New	Normal		Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.4-support-8G-DDR-UI-20250416	sun	05/13/2025 11:41 AM
944	LP162	Bug	New	Low	hwclock -w Local time/Universal time	Ubuntu	\\192.168.1.250\01-Public\volcan\3588\LPB3588\LPB3588_ubuntu22.04_v1.0_20250415_1639.img	sun	05/13/2025 03:25 PM
943	LZ210	Bug	New	High	RK3562J 70° DCDC	Ubuntu	rk3562_ubuntu2204_20250409A.img	zenghui	05/12/2025 06:43 PM
942	LP162	Bug	New	Normal	MIC	Ubuntu	\\192.168.1.250\01-Public\volcan\3588\LPB3588\LPB3588_ubuntu22.04_v1.0_20250415_1639.img	sun	05/13/2025 03:25 PM
941	LB700	Bug	New	Normal	TF	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.4-support-8G-DDR-UI-20250416	sun	05/12/2025 02:47 PM
940	LZ750	Bug	New	Normal	DDR	Ubuntu		sun	05/12/2025 01:44 PM
939	LZ230	Bug	New	Normal	u	Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot		05/13/2025 11:33 AM
938	LZ230	Bug	New	Normal	iwconfig/lbblk/ffprobe/lftp/iperf3/at/timedatectl	Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot		05/13/2025 11:52 AM
937	LZ230	Bug	New	Normal	sudo/glmark2-es2/gst-launch-1.0		01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot		05/13/2025 11:54 AM
936	LZ230	Bug	New	Low			01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot	zenghui	05/09/2025 05:27 PM
935	LZ230	Bug	New	Normal	FAT32 u	Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot		05/09/2025 05:27 PM
934	LZ230	Bug	New	High	NTFS u	Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot		05/09/2025 05:27 PM
933	LZ230	Bug	New	High	arecord	Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot		05/08/2025 02:27 PM
932	LZ230	Bug	New	Normal	WiFi	Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot		05/07/2025 04:39 PM

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
931	LZ230	Bug	New	High	MASKROOM		01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot	zenghui	05/06/2025 10:38 AM
930	LZ230	Bug	New	High	MIPI TP Screen	Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot	zenghui	04/30/2025 05:50 PM
929	LZ230	Bug	New	High	MIC1&2	Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot		04/30/2025 05:44 PM
928	LZ230	Bug	New	High	rootfs adb	Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot		04/30/2025 05:40 PM
927	LZ230	Bug	New	High	USB	Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot	Linx	04/30/2025 05:38 PM
926	LZ230	Bug	New	High	reset update	Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot	zenghui	05/06/2025 06:38 PM
925	LZ230	Bug	New	High	REST update	Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot	zenghui	05/06/2025 06:37 PM
924	LP11A	Bug	New	Normal	RS232/RS485/GPIO Vcc_Out 1A	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\v03	jing	04/25/2025 02:10 PM
923	LZ210	Bug	New	Urgent	RK3562J sudo -i cpu	Ubuntu	rk3562_ubuntu2204_20250409A.img	Linx	05/09/2025 01:49 PM
921	LZ750	Bug	New	Urgent	1000M	Ubuntu	fastboot kernel \\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs \\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	04/03/2025 02:59 PM
920	LZ750	Bug	New	High	audio demo	Ubuntu	fastboot kernel \\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs \\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/03/2025 02:57 PM
919	LZ750	Bug	New	Urgent	gpio50	Ubuntu	fastboot kernel \\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs \\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	04/03/2025 02:43 PM
918	LZ750	Bug	New	Urgent	USB 100M ssh camera	Ubuntu	fastboot kernel \\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs \\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	04/03/2025 02:28 PM
917	LZ750	Bug	New	High	IP	Ubuntu	fastboot kernel \\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs \\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/02/2025 06:18 PM
916	LZ700(LD700)	Bug	New	High	IP	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/02/2025 06:16 PM
915	LZ750	Bug	New	High	neardi		fastboot kernel \\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs \\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	04/08/2025 06:20 PM
914	LZ750	Bug	New	Urgent	Out of memory		fastboot kernel \\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs \\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	04/08/2025 06:19 PM
913	LZ750	Bug	New	High	J2600--normal		fastboot kernel \\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs \\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	04/02/2025 05:29 PM
912	LZ750	Bug	New	High	J2903--TP		fastboot kernel \\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs \\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	04/02/2025 05:28 PM

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
911	LZ750	Bug	New	High	J2904--30pin FPC		fastboot\kernel\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	04/02/2025 05:25 PM
910	LZ750	Bug	New	High		Ubuntu	fastboot\kernel\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	04/02/2025 05:18 PM
909	LZ750	Bug	New	Urgent	ddr	Ubuntu	fastboot\kernel\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/02/2025 05:38 PM
907	LZ210	Bug	New	Urgent	usb3.0hub	Ubuntu	192.168.1.250\01-Public\Linx\rk3562\20250321	Linx	04/01/2025 09:46 AM
905	LZ700(LD700)	Bug	New	Urgent	ddr	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	03/31/2025 05:50 PM
904	LZ700(LD700)	Bug	New	High	Neardi		192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/01/2025 03:31 PM
902	LZ700(LD700)	Bug	New	High	camera	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/01/2025 03:36 PM
901	LZ700(LD700)	Bug	New	High	USB 100M ssh camera	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/01/2025 03:33 PM
900	LZ700(LD700)	Bug	New	High	audio demo	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	03/27/2025 05:30 PM
899	LZ700(LD700)	Bug	New	High	J2904--30pin FPC	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	03/27/2025 04:57 PM
898	LZ700(LD700)	Bug	New	High	J2903--TP	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	03/27/2025 04:46 PM
897	LZ700(LD700)	Bug	New	High	J2600--normal	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	03/27/2025 04:42 PM
896	LZ700(LD700)	Bug	New	High	npd demo	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	03/27/2025 05:35 PM
895	LZ700(LD700)	Bug	New	Urgent	PCIE M.2	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	03/27/2025 04:36 PM
894	LZ700(LD700)	Bug	New	High		Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	03/27/2025 04:36 PM
893	LZ700(LD700)	Bug	New	Urgent	1000M	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	03/27/2025 04:36 PM
886	LP160	Bug	New	High	HDMI	Android	192.168.1.250\03-image\rk3588-a12\LKD3588-\kd3588-android12-V3-fd7352s-bt-ok-20250114\kd3588-android12-V3-fd7352s-bt-ok-20250114.img	sun	03/17/2025 09:47 AM
885	KP12C	Bug	New	Urgent	FD7352Wifi	Ubuntu	192.168.1.250\01-Public\wilson_test\rk3568\kp12c\KP12C_4_1080_Ubuntu20.04_v1.0_20250117		03/17/2025 09:40 AM

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
884	LZ201	Bug	New	Urgent	can't boot from USB drive	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\Linux\2025_03_10		03/11/2025 04:22 PM
879	LB700	Bug	New	High	USB-C to HDMI adapter not working	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250314	Linx	03/14/2025 03:26 PM
874	LB700	Bug	New	High	J2904--30pin FPC not working	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304		03/06/2025 03:19 PM
872	LB700	Bug	New	Normal	camera module not working	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	04/18/2025 06:37 PM
871	LB700	Bug	New	High	Bluetooth module not working	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/07/2025 05:23 PM
868	LP201	Bug	New	High	USB-C to USB-A adapter not working	Ubuntu	-		03/04/2025 07:46 PM
867	LP201	Bug	New	High	USB-C to USB-A adapter not working	Ubuntu	-		03/04/2025 07:44 PM
866	LP201	Bug	New	Urgent	TYPE-C/SIM card not working	Ubuntu	-		03/04/2025 06:57 PM
865	LP201	Bug	New	High	USB-C to USB-A adapter not working	Ubuntu	-		03/04/2025 06:40 PM
864	LP201	Bug	New	High	U9606/U9607/U9608 not working	Ubuntu	-		03/04/2025 06:08 PM
863	LP201	Bug	New	High	M4 module not working	Ubuntu	-		03/04/2025 05:21 PM
862	LP201	Bug	New	Normal	USB-C to USB-A adapter not working	Ubuntu	-		03/04/2025 04:38 PM
860	LP201	Bug	New	High	CR module not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	03/04/2025 03:09 PM
857	LP201	Bug	New	High	RTC module not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	03/03/2025 04:04 PM
855	LZ750	Bug	New	High	USB-C to USB-A adapter not working	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	sun	02/28/2025 02:14 PM
854	LZ750	Bug	New	Normal	USB-C to USB-A adapter not working	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	Linx	02/28/2025 02:23 PM
852	LB200	Bug	New	Urgent	type-c module not working		\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2025_02_27\rk3576_lb200_ubuntu2204_25_02_27.img		02/28/2025 11:25 AM
851	LP201	Bug	New	High	USB-C to USB-A adapter not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img		02/27/2025 06:53 PM
850	LZ750	Bug	New	High	MIC module not working	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	jing	02/28/2025 02:18 PM
849	LZ750	Bug	New	High	MINI PCIE module not working	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	jing	02/27/2025 05:15 PM
848	LZ750	Bug	New	Urgent	PCIE module not working	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	jing	02/27/2025 04:25 PM
847	LZ750	Bug	New	High	5G module not working	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	sun	02/28/2025 02:17 PM

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
845	LB200	Bug	New	High	USB3.0 HUB 无法识别设备	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	Linx	02/27/2025 03:25 PM
844	LB700	Bug	New	High	audio 播放 demo 音频文件失败	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	04/18/2025 06:38 PM
840	LB200	Bug	New	Normal	无法识别 mmcblk0 和 mmcblk1	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	Linx	02/18/2025 05:20 PM
837	LB200	Bug	New	Urgent	USB3.0 3.0U 无法识别		\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	yuncaic	02/18/2025 02:23 PM
836	LB200	Bug	New	Normal	无法识别设备		\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	Linx	02/17/2025 03:31 PM
835	Wifi_Factory_Test	Bug	New	Normal	WiFi 无法连接				02/14/2025 04:11 PM
834	LZ201	Bug	New	Normal	HDMI 无法识别 SPK	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/14/2025 02:42 PM
833	LZ201	Bug	New	Normal	4g eth0 无法识别 4g DNS	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	Linx	02/13/2025 05:58 PM
832	LZ201	Bug	New	Normal	SPK 无法识别	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/13/2025 01:51 PM
831	LZ201	Bug	New	Normal	无法识别 pop 和 reboot	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/13/2025 01:46 PM
829	LZ201	Bug	New	Normal	HDMI type-c DP 无法识别	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	Linx	02/10/2025 02:08 PM
828	LZ201	Bug	New	Low	无法识别 4.78GB 4GB	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	Linx	02/10/2025 04:08 PM
827	LZ201	Bug	New	High	TP 无法识别	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/08/2025 06:15 PM
826	LZ201	Bug	New	High	MIPI DSI TX mipi 无法识别	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/08/2025 06:13 PM
825	LZ201	Bug	New	High	WORK 无法识别	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/08/2025 11:34 AM
824	LZ201	Bug	New	Normal	无法识别 eth0 LED	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/06/2025 03:25 PM
822	LZ201	Bug	New	Normal	无法识别 root gst-launch-1.0	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	Linx	02/06/2025 02:00 PM
821	LZ201	Bug	New	Urgent	MIPI 无法识别 3A	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	Linx	02/06/2025 01:40 PM
819	LP201	Bug	New	Normal	无法识别 2280M.2	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/23/2025 09:52 AM
818	LP201	Bug	New	High	HDMI 无法识别 FPC	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/22/2025 12:00 PM
817	LP201	Bug	New	High	无法识别 SIM	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/22/2025 10:56 AM
816	LP201	Bug	New	High	rootfs 无法识别 NetworkManager-wait-online.service 27.848s	Ubuntu	ubuntu22.04_lb201_25_01_07.img	Linx	01/22/2025 11:46 AM
815	LP201	Bug	New	High	无法识别 HDMI LCD	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/22/2025 10:06 AM
814	LP201	Bug	New	Normal	ubuntu 无法识别 debian 1080P30 1080P60 buildroot	Ubuntu	ubuntu22.04_lb201_25_01_07.img	Linx	01/21/2025 04:23 PM
813	LP201	Bug	New	High	无法识别 D/I GPIO55	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/21/2025 03:56 PM
812	LP201	Bug	New	High	D/O 无法识别 12V	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/21/2025 10:54 AM

#	Project	Tracker	Status	Priority	Subject	OS	Image	Assignee	Updated
811	LP201	Bug	New	Normal	reboot--SPKpop	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/22/2025 11:01 AM
809	LP201	Bug	New	High	Type-C	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/16/2025 05:56 PM
808	KP12C	Bug	New	High	LP120_4_1080_Ubuntu20.04_v1.0_20250110.img TF	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img		01/15/2025 05:55 PM
807	Wifi_Factory_Test	Bug	New	Urgent	Wifi				02/14/2025 04:15 PM
806	Wifi_Factory_Test	Bug	New	High					01/15/2025 03:45 PM
805	Wifi_Factory_Test	Bug	New	Normal	Wifi				01/15/2025 03:42 PM
804	Wifi_Factory_Test	Bug	New	Normal	XWGageBUG				01/15/2025 04:30 PM
803	Wifi_Factory_Test	Bug	New	High	wifi1m				01/15/2025 03:32 PM
802	Wifi_Factory_Test	Bug	New	Normal	wifi				01/15/2025 03:28 PM
801	Wifi_Factory_Test	Bug	New	Urgent	Wifi				01/15/2025 03:26 PM
800	Wifi_Factory_Test	Bug	New	High	Wifi				02/06/2025 10:24 AM
799	Wifi_Factory_Test	Bug	New	Normal	Wifi				01/15/2025 03:18 PM
796	KP12C	Bug	New	Normal	usb2.0usb3.0 hub 30%	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img	Linx	01/14/2025 11:54 AM
795	KP12C	Bug	New	Normal	AHD	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img		01/13/2025 09:55 AM
793	WIFI	Bug	New	Normal	FD7352S-BS AP		rk3588_debian_wifi_test_7352s_h24.45-B_12_30.img		01/09/2025 01:50 PM
792	LP201	Bug	New	High	LCD	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/09/2025 10:04 AM
791	KP12C	Bug	New	Urgent	TF	Ubuntu	LP120_4_1080_Ubuntu20.04_v1.0_20240929.img		01/10/2025 10:33 AM
790	LP201	Bug	New	High		Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/08/2025 08:02 PM
789	LP201	Bug	New	High	RS485/CAN	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/08/2025 07:57 PM
787	LP201	Bug	New	Urgent	3-5	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/22/2025 10:42 AM
786	LZ130	Bug	New	High		Ubuntu		jing	01/08/2025 05:48 PM
785	LP201	Bug	New	Immediate		Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/08/2025 06:19 PM

#	Project	Tracker	Status	Priority	Subject	OS	File Name	Assignee	Updated
784	WIFI	Bug	New	Urgent	FD7352S-BS For LKD3588 iperf3 -c udp iperf3 -s	Debian	rk3588_debian_wifi_test_7352s_h24.45-B_12_30.img		01/09/2025 03:37 PM
783	WIFI	Bug	New	Urgent	FD7352S-BS STA AX80 udp	Debian	rk3588_debian_wifi_test_7352s_h24.45-B_12_30.img		01/09/2025 01:43 PM
782	LP201	Bug	New	High	eth1	Ubuntu	ubuntu22.04_lb201_25_01_07.img		02/26/2025 03:49 PM
781	LP201	Bug	New	High	DC/IN	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/08/2025 11:32 AM
780	LZ210	Bug	New	Low	C2045 J9200	Ubuntu	rk3562_lkd210_ubuntu22.04_12_29.img	zenghui	01/08/2025 10:47 AM
778	KP12C	Bug	New	High	AHD	Ubuntu	LP120_4_1080_Ubuntu20.04_v1.0_20240929.img		01/06/2025 09:08 PM
776	LP112	Bug	New	High	USB2.0 USB1.0	Ubuntu	LZ112_3588_ubuntu20.04_v1.0_20240204_1649		01/02/2025 02:05 PM
775	LPM3568	Bug	New	Normal	ETH ifconfig	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	Linx	12/31/2024 03:39 PM
774	LZ210	Bug	New	High	SARADC0_IN6 1.8V GND 1 .3V	Ubuntu	rk3562_lkd210_ubuntu22.04_12_29.img	zenghui	01/06/2025 11:14 AM
773	WIFI	Bug	New	Normal	FD7352S HE-MCS	Debian	rk3588_debian_wifi_test_7352s_h24.45-B_12_30.img		12/30/2024 06:36 PM
771	LZ210	Bug	New	High		Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/27/2024 09:06 PM
770	LZ210	Bug	New	Normal	ADC_IN voltage_raw 0	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/27/2024 05:44 PM
769	LZ210	Bug	New	Urgent	ADC_IN 0.1V	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/27/2024 05:46 PM
768	LZ130	Bug	New	Urgent	15mm	Ubuntu			01/03/2025 06:33 PM
766	LZ210	Bug	New	High	Ubuntu --	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	12/26/2024 04:31 PM
763	LZ210	Bug	New	Normal	4k	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	12/25/2024 08:18 PM
761	WIFI	Bug	New	Normal	FD7352S-BS	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu		12/27/2024 10:28 AM
760	WIFI	Bug	New	Normal	FD7352S-BS	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu		12/25/2024 06:05 PM
752	WIFI	Bug	New	High	FD7352S-BS AP	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu		12/27/2024 10:25 AM
749	LB700	Bug	New	High		Ubuntu		shiliang	12/23/2024 04:05 PM
748	LZ210	Bug	New	High	root gst-	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	01/10/2025 10:15 AM
747	LB700	Bug	New	High	4	Ubuntu		shiliang	12/23/2024 02:34 PM
746	LB700	Bug	New	Normal		Ubuntu		shiliang	12/23/2024 02:27 PM
745	LB700	Bug	New	High		Ubuntu		shiliang	12/23/2024 02:24 PM
743	LZ210	Bug	New	High	MIPI 3A	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	05/09/2025 01:57 PM
742	LZ210	Bug	New	High	POP	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/24/2024 04:53 PM
739	LP11A	Bug	New	High	LP11A				12/20/2024 06:19 PM
738	LZ210	Bug	New	High	LC210 SOC	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img		12/20/2024 04:24 PM

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
737	LP160	Bug	New	High	12v16v15v16vAHD	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	jing	01/17/2025 03:55 PM
736	LZ210	Bug	New	High	USB2.04G	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	05/13/2025 11:52 AM
734	LB700	Bug	New	High	demo	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/07/2025 05:24 PM
733	LZ210	Bug	New	Normal		Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	05/12/2025 06:45 PM
731	LZ210	Bug	New	High	power system	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	01/06/2025 11:18 AM
728	LZ210	Bug	New	High	power	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	05/13/2025 11:50 AM
724	LB200	Bug	New	Normal					02/17/2025 01:48 PM
721	LB200	Bug	New	High		Ubuntu			02/17/2025 01:56 PM
719	LB200	Bug	New	High					02/17/2025 01:56 PM
718	LZ210	Bug	New	Low	4.77 GB4GB	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	k	05/13/2025 11:41 AM
717	LB700	Bug	New	High	thermal dmc cpufreq	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	sun	03/07/2025 02:44 PM
714	LB700	Bug	New	High	U050145°C	Ubuntu	https://forum.neardi.com/d/126-hisi3403-xia-zai-gu-jian	jing	12/16/2024 06:25 PM
713	LP620	Bug	New	Urgent	USB/Type-C	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/13/2024 09:18 PM
712	LP620	Bug	New	Normal	J3200 GPIO	Ubuntu	Linux_for_Tegra.tar.gz		12/13/2024 08:51 PM
711	LP620	Bug	New	Normal	MCP2515CAN2&3	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/13/2024 08:13 PM
710	LP620	Bug	New	Urgent	RS485 ttysWK0/ttysWK1	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/13/2024 07:55 PM
709	LP620	Bug	New	Normal	J3304/J3303 RS485 AB	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/13/2024 07:49 PM
707	LP620	Bug	New	Normal	J3300 PWM	Ubuntu	Linux_for_Tegra.tar.gz		12/13/2024 06:02 PM
706	LP620	Bug	New	Normal	LED	Ubuntu	Linux_for_Tegra.tar.gz		12/13/2024 05:57 PM
704	LP620	Bug	New	Normal	WIFI/BT	Ubuntu	Linux_for_Tegra.tar.gz		12/13/2024 04:25 PM
700	LB700	Bug	New	Normal	J2500	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	shiliang	03/06/2025 03:20 PM
699	LB700	Bug	New	High	J2903--TP	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	sun	03/06/2025 03:25 PM
695	LP620	Bug	New	Normal	MIPI TX/MIPI CSI Rx	Ubuntu	Linux_for_Tegra.tar.gz		12/23/2024 10:30 AM
694	LP620	Bug	New	Normal	4Gquectel-CM	Ubuntu	Linux_for_Tegra.tar.gz	Linx	12/13/2024 02:05 PM
690	LB700	Bug	New	Normal	Mini-PCIE1808	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	sun	03/17/2025 11:04 AM
689	LB700	Bug	New	Normal	Mini-PCIE	Ubuntu	https://forum.neardi.com/d/126-hisi3403-xia-zai-gu-jian	shiliang	12/13/2024 10:41 AM
685	LP620	Bug	New	High	Master SSD	Ubuntu	Linux_for_Tegra.tar.gz		12/12/2024 06:53 PM
683	LP620	Bug	New	Normal	TXETH1)	Ubuntu	Linux_for_Tegra.tar.gz		12/12/2024 05:45 PM

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
642	LP160	Bug	New	Normal	A/i	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	jing	01/14/2025 05:51 PM
639	LP620	Bug	New	Urgent	J3300 12V4.84	Ubuntu	Linux_for_Tegra.tar.gz	jing	11/21/2024 04:20 PM
638	LP620	Bug	New	High	4K	Ubuntu	Linux_for_Tegra.tar.gz	Linx	11/21/2024 10:28 AM
637	LP620	Bug	New	High	M.2 Slot M3.0	Ubuntu	Linux_for_Tegra.tar.gz	jing	11/20/2024 04:11 PM
636	LP620	Bug	New	Immediate	PCIe3.0 SSD	Ubuntu	Linux_for_Tegra.tar.gz	jing	11/20/2024 03:53 PM
635	LP122	Bug	New	Urgent	HDMI	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu	sun	01/15/2025 09:55 AM
634	LP122	Bug	New	High	wifi HE-MCS	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu		11/15/2024 05:26 PM
632	LB200	Bug	New	High	BT	Ubuntu	rk3576_lb200_ubuntu2204_12_03.img		02/21/2025 04:01 PM
627	LB200	Bug	New	Normal	J2800 USB USB	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu2204_11_11.img		11/14/2024 03:19 PM
625	LB200	Bug	New	Normal	Type-C	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu2204_11_11.img		12/04/2024 04:48 PM
624	LB200	Bug	New	Normal	Type-C debug	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu2204_11_11.img		12/04/2024 04:48 PM
623	LB200	Bug	New	Urgent	5G	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu2204_11_11.img		12/09/2024 10:15 AM
620	LB200	Bug	New	High		Ubuntu	rk3576_lb200_ubuntu22.04_20241108A.img		12/06/2024 04:59 PM
619	LB200	Bug	New	Normal	J4500/J4501	Ubuntu	rk3576_lb200_ubuntu22.04_20241108A.img		11/13/2024 09:09 PM
615	LP122	Bug	New	High	4G	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu		01/17/2025 11:33 AM
609	LP122	Bug	New	Urgent	HDMI2 HDMI	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu	jing	11/15/2024 04:34 PM
608	LPM3568	Bug	New	Normal		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test		11/26/2024 02:32 PM
607	LPM3568	Bug	New	Normal		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	Linx	11/08/2024 06:40 PM
606	LPM3568	Bug	New	Urgent		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test		11/08/2024 06:17 PM
605	LPM3568	Bug	New	Normal	HDMI	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	Linx	11/29/2024 10:09 AM
603	LPM3568	Bug	New	Normal	wifi HE-MCS	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test		11/08/2024 10:52 AM
601	LPM3568	Bug	New	Normal	USB2.0 USB3.0	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	jing	11/08/2024 11:41 AM
600	LPM3568	Feature	New	Normal	USB	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	jing	11/08/2024 11:55 AM
598	LPM3568	Bug	New	Low	ETH1	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test		11/07/2024 04:07 PM
597	LPM3568	Bug	New	Normal	emmc	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	Linx	11/07/2024 04:07 PM

#	Project	Tracker	Status	Priority	Subject	OS	File Name	Assignee	Updated
592	LP11A	Bug	New	Urgent	reboot	Ubuntu	LP11A_Ubuntu18.04_v3.0_20240930_Test.img		11/05/2024 10:28 AM
587	LP160	Bug	New	Urgent	16v AHD	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	jing	04/15/2025 05:03 PM
585	LP160	Bug	New	Urgent	HDMI	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	Linx	01/14/2025 05:50 PM
584	LP160	Bug	New	Normal	M.2 SSD	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	Linx	01/15/2025 11:23 AM
583	LP160	Bug	New	High	4pin speaker	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	sun	10/30/2024 09:58 AM
582	LP160	Bug	New	Normal	TF	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	Linx	01/14/2025 06:30 PM
581	LP160	Bug	New	Urgent	AHD	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu		11/01/2024 10:10 AM
580	LP11A	Bug	New	Normal					10/30/2024 04:49 PM
579	LP11A	Bug	New	Normal	PCBA		/		10/30/2024 04:48 PM
576	LP120	Feature	New	Urgent	FPGA	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568	jing	01/17/2025 02:06 PM
570	KZ117	Bug	New	High	mac mac iP	Ubuntu	rk3399pro_KZ117_ubuntu_gaussion_ddr3_20240628.img	Linx	11/25/2024 03:32 PM
565	LP122	Bug	New	Urgent	USB	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu\LPB3568_ubuntu20.04_HDMI_v1.0_20240524_1358	sun	10/29/2024 09:36 AM
562	KD16C()	Bug	New	Normal	wifi_ping waln ping wifi IP	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240806v2.0.img		09/23/2024 11:30 AM
556	WIFI	Bug	New	Urgent	FD7352S, STA 5G/2.4G mcs	Ubuntu	update-sdio.img		09/14/2024 02:28 PM
555	WIFI	Bug	New	Urgent	FD7352S/P AP SSID	Ubuntu	update-sdio.img		12/18/2024 07:30 PM
553	WIFI	Bug	New	High	FD7352P, STA 2.4G ax-40 tx mcs 11 mcs 11	Ubuntu	update-pcie.img		09/12/2024 01:45 PM
552	WIFI	Bug	New	High	FD7352P, STA ac-80 iperf3	Ubuntu	update-pcie.img		09/12/2024 10:31 AM
551	WIFI	Bug	New	High	AP6275S LPA3588 AP 70%	Ubuntu	update.img	sun	09/11/2024 06:42 PM
550	WIFI	Bug	New	High	FD7352P, STA 2.4G n only rx ac n ac	Ubuntu	update-pcie.img		09/10/2024 04:59 PM
549	WIFI	Bug	New	High	FD7352P, ax80 tx 70. 800~900Mbps/sec 750 Mbps/sec	Ubuntu	update-pcie.img		09/12/2024 01:48 PM
546	LP120	Bug	New	Normal	TF U	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568		09/05/2024 03:17 PM

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
543	LP120	Bug	New	Immediate	XXXXXXXXXXXX	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568	jj	01/17/2025 02:00 PM
535	LP120	Feature	New	Normal	XXXXXXXXXXXX	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568	jing	10/23/2024 04:31 PM
525	LP11A	Bug	New	Normal	ESD -8KV 485/gpioXXXXXXXXXX		-		10/30/2024 04:44 PM
517	KD16C(DD)	Bug	New	High	XXXX_X_Y_XXXXXXXXXXXXXXXXXXXX	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240806v2.0.img	jjj	08/13/2024 03:14 PM
514	LP11A	Bug	New	Normal	XXXXXXXXXX_XXXXXX			j	08/27/2024 10:22 AM
508	KD16C(DD)	Bug	New	Normal	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240702v1.0.img		08/07/2024 10:40 AM
500	KD16C(DD)	Bug	New	High	SIMXXXXXXXXXXXX	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240702v1.0.img	jjj	07/24/2024 11:50 AM
496	LCS3588(LC166)	Bug	New	Normal	gpioXXXXXX	Ubuntu	lkd3588-t0-ubuntu-240718.img	sun	07/22/2024 11:30 AM
494	LP11A	Feature	New	Low	-20XXXXXXXXXX4AHDXXXX_KP11A	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V3.2	Linx	11/07/2024 02:05 PM
492	KD17A	Bug	New	High	KD17A,iperf3XXXXXXXXXXXXXXXXXXXX100Mbps/sec .XXXX500-600Mbps/sec	Ubuntu	KZ17A_ubuntu20.04_v1.9_fixed_fd7352s_crash_20240708.img	sun	07/17/2024 02:16 PM
489	KD17A	Bug	New	Urgent	XXXXXXXXXXXXXXXXXXXXsdioXXXXXX	Ubuntu	KZ17A_ubuntu20.04_v1.8_yt8521_driver_strength_20240704.img	jing	07/16/2024 11:05 AM
486	LP160	Bug	New	Normal	LKD3588_Debian_UXXXXXX	Debian		Linx	07/15/2024 07:06 PM
483	LCS3588(LC166)	Bug	New	Normal	XXXXXXXXXXXXXXXXXXXX	Ubuntu	lkd3588-t0-ubuntu-240703.img	sun	07/10/2024 06:09 PM
482	LCS3588(LC166)	Bug	New	High	LVDSXXXXXXLD166XXXXXXXXXXLVDSXX	Ubuntu	lkd3588-t0-ubuntu-240703.img	sun	07/10/2024 04:08 PM
481	LCS3588(LC166)	Bug	New	Normal	btXXXXXX	Ubuntu	lkd3588-t0-ubuntu-240703.img	sun	07/10/2024 04:08 PM
480	LCS3588(LC166)	Bug	New	Normal	wifiXXXXXX	Ubuntu	lkd3588-t0-ubuntu-240703.img	sun	07/10/2024 04:07 PM
476	KD16C(DD)	Bug	New	High	USB1_3.0UXXXX2.0XXXXXXXX3.0XXXX	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240702v1.0.img	shiliang	07/08/2024 06:18 PM
472	KD16C(DD)	Bug	New	High	12V OUTXXXXXXXXXXXX11.2VXXXX	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-v1.0.img	jing	07/01/2024 04:26 PM
471	LZ166	Bug	New	Urgent	linuxXXXXXXXXXXXXTXXXXXX	Ubuntu	update.img	jj	07/12/2024 10:18 AM
464	KZ16E	Bug	New	High	MM.2XXXX	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\XXXXXXXXXXXXXXXXXXXXpcie3.0XXXXXXXXXXXXXXXXXXXX\LKD3588_ubuntu20.04_v1.0_20240523_1544.img	sun	06/14/2024 02:33 PM
439	LB120	Bug	New	High	LB120XXXXXXXXXXXXeth1XXXXXXXX350XX	Ubuntu	LBA3568_ubuntu20.04_v1.0_20240301_2020.img	Linx	03/29/2024 10:58 AM
438	PPX30	Bug	New	Normal	LCM XXXXXXXX		-	shiliang	03/18/2024 05:02 PM

#	Project	Tracker	Status	Priority	Subject	OS	Image	Assignee	Updated
436	PX30	Bug	New	Normal	APP 无法安装	Android	PX30_Test_V01_20240308.img		03/12/2024 05:57 PM
435	KD17A	Bug	New	High	KD17A 无法连接 AP 无法连接 SSID, 无法连接 WiFi	Ubuntu	update.img	sun	03/12/2024 03:11 PM
434	LP122	Bug	New	Urgent	5G (RM500U-CNV) 无法	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230801_1621.img	Linx	09/25/2024 04:23 PM
433	PX30	Bug	New	Normal	KB19B 无法连接		-	jing	11/14/2023 09:28 PM
432	LP160	Bug	New	Normal	CAN 无法 loopback	Ubuntu		sun	11/08/2023 05:37 PM
426	PX30	Bug	New	Normal	无法 lanuch 无法 Ui 无法	Android	update-android-v8.0.3-20231019.img	sun	10/20/2023 02:19 PM
425	PX30	Bug	New	Normal	无法 APP Stopping	Android	update-android-v8.0.1.img		10/19/2023 07:15 PM
424	PX30	Bug	New	Normal	Power ON/OFF NG	Android	update-android-v8.0.1.img	sun	10/19/2023 07:11 PM
423	PX30	Bug	New	Normal	无法 recovery	Android	update-android-v8.0.1.img		10/19/2023 07:05 PM
422	PX30	Bug	New	Normal	ADB 无法	Android	update-android-v8.0.1.img	jing	10/20/2023 12:53 PM
420	LP160	Bug	New	Urgent	LPA3588 无法 12H 无法	Ubuntu		sun	10/17/2023 09:49 AM
419	LP160	Bug	New	Urgent	3588 无法 40-50ms 无法 100ms	Ubuntu		Linx	10/16/2023 11:27 AM
418	LP160	Bug	New	Urgent	LPA3588 无法	Ubuntu		sun	10/16/2023 11:23 AM
410	LP162	Bug	New	Urgent	HDMI3 无法	Ubuntu	LZ160XXX03_RL_AC_F1_230914A-3588-Android12.img	sun	09/21/2023 11:45 AM
408	LP160	Bug	New	High	无法 sony1.mp4 ch-test .wav	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/13/2023 11:49 AM
407	LP160	Bug	New	High	HDMI_OUT3 无法	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/13/2023 10:06 AM
406	LP162	Bug	New	High	无法 sony1.mp4 ch-test .wav	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/11/2023 05:46 PM
391	FAE	Issues	Feedback	Normal	Ubuntu 无法 Protocol not available				08/25/2023 06:51 PM
390	FAE	Issues	Feedback	Normal	linux 无法 cpu 无法				08/02/2023 04:15 PM
389	FAE	Issues	Feedback	Normal	ssh 无法				08/01/2023 02:24 PM
388	LP162	Feature	New	High	can 无法 3588 无法	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/26/2023 02:44 PM
387	FAE	Issues	Feedback	Normal	Android12 HDMI 无法				07/31/2023 11:55 AM
386	FAE	Issues	Feedback	Normal	Linux 无法				07/24/2023 07:03 PM
385	FAE	Issues	Feedback	Normal	LPB3399Pro LZ112 无法 adb				07/24/2023 10:39 AM
380	LP122	Bug	New	High	RS232 无法 --COM3 无法 ttysWK3	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	sun	07/10/2023 11:57 AM

#	Project	Tracker	Status	Priority	Subject	OS	Image	Assignee	Updated
376	LP122	Bug	New	Normal	./rockchip-test/npu2rknn_demo.sh npu_freq_scaling.sh	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	Linx	11/14/2023 04:02 PM
372	LP122	Bug	New	High	HDMI-RX video1	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	sun	07/04/2023 11:49 AM
370	LP160	Bug	New	Normal	USB type-c USB	Android	LZ160_3588_Android12_v1.0_20230629.img	sun	07/03/2023 03:42 PM
367	LP122	Bug	New	Normal	SD SD	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	sun	06/30/2023 05:50 PM
366	LP122	Bug	New	Normal	UnixBench Glmark2-es2 Stream	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	Linx	11/14/2023 03:26 PM
365	LP122	Bug	New	Normal	A/INI1234	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	sun	06/30/2023 05:50 PM
354	LB170	Bug	New	Normal	LB170, M.2	Ubuntu	lb170_3588_ubuntu20.04_v1.0_20230607_1025.img	sun	06/27/2023 10:51 AM
348	KZ117	Bug	New	Normal	LVDS	Ubuntu	Factory_Image		07/11/2023 03:22 PM
342	LP112	Bug	New	Normal	usb3.0 3.0U	Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704		07/03/2023 11:33 AM
339	LP112	Bug	New	Normal		Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704	Linx	07/18/2023 04:25 PM
338	LP112	Bug	New	High		Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704	Linx	07/14/2023 10:35 AM
337	LP112	Bug	New	High		Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704		07/18/2023 04:22 PM
334	LP162	Bug	New	Normal	HDMI-OUT3	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/11/2023 06:16 PM
331	LP162	Bug	New	Normal	A/INI1234	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	sun	05/12/2025 11:56 AM
330	LP162	Bug	New	Normal	Connection Failed Protocol not available.	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/11/2023 03:49 PM
329	LP162	Bug	New	Normal	pop	Ubuntu	RK3588_UBUNTU_V1_230519.img	sun	06/09/2023 05:49 PM
328	LP162	Bug	New	Normal	POP	Ubuntu	RK3588_UBUNTU_V1_230519.img	sun	06/09/2023 05:47 PM
327	LP162	Bug	New	Normal	"mpv Media Player" "8k.mp4"	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/11/2023 03:57 PM
326	LP162	Bug	New	Normal	"mpv Media Player" "jellyfish-140-mbps-4k-uhd-hevc-10bit.mkv"	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/11/2023 03:58 PM
323	LP162	Bug	New	Normal	2.03.0 ext4	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/11/2023 03:29 PM
319	LP162	Bug	New	High	4 COM RS232	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/18/2023 03:40 PM
316	LP160	Bug	New	Normal	LPA3588_Ubuntu 20.04.5_HDMI HDMI OUT3	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/13/2023 10:14 AM
311	LP160	Bug	New	Normal	LPA3588_Ubuntu 20.04.5 M.2 ext4	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/13/2023 03:44 PM
310	LP160	Bug	New	Normal	LPA3588_Ubuntu 20.04.5 A/INI1234	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/12/2023 04:45 PM

#	Project	Tracker	Status	Priority	Subject			Assignee	Updated
206	FAE 00	Issues	Feedback	Normal	Ubuntu18.04 000000				12/09/2022 02:10 PM
187	FAE 00	Issues	Feedback	Normal	000000				11/21/2022 12:04 AM
186	FAE 00	Issues	Feedback	Normal	Linux USB 000				11/20/2022 11:55 PM
185	FAE 00	Issues	Feedback	Normal	Linux 000000				11/17/2022 07:24 PM
184	FAE 00	Issues	Feedback	Normal	Buildroot tcpchecksum000				11/17/2022 05:15 PM
183	FAE 00	Issues	Feedback	Normal	Android9 HDMI				11/17/2022 04:48 PM
182	FAE 00	Issues	Feedback	Normal	Ubuntu18.04 sqlite30000				11/17/2022 04:45 PM
181	FAE 00	Issues	Feedback	Normal	Ubuntu000Qemu Unsupported00				12/07/2022 05:23 PM
180	FAE 00	Issues	Feedback	Normal	Android12 00tv_input00				11/17/2022 11:59 AM
179	FAE 00	Issues	Feedback	Normal	Ubuntu22.04000000				11/17/2022 11:50 AM
178	FAE 00	Issues	Feedback	Normal	Ubuntu0000000000				11/17/2022 11:50 AM
177	FAE 00	Issues	Feedback	Normal	Ubuntu0000000000				01/17/2023 06:05 PM
176	FAE 00	Issues	Feedback	Normal	Ubuntu00mpp				01/17/2023 09:52 AM
175	FAE 00	Issues	Feedback	Normal	Ubuntu22.0400000000				11/17/2022 11:49 AM
174	FAE 00	Issues	Feedback	Normal	00USB00000000				11/17/2022 11:51 AM
11	Android_10	Release	New	Normal	LBD3399_android10_R10_QA_A_V0.2_20201222			mike	01/04/2021 03:31 PM
5	Android_10	Release	New	Normal	LBD3399_android10_R10_QA_A_V0.1_20201210			mike	12/22/2020 06:32 PM