

Issues

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
924	LP11A	Bug	New	Normal	RS232/RS485/GPIO Vcc_Out 1A	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\03	jing	04/25/2025 02:10 PM
919	LZ750	Bug	New	Urgent	gpio50	Ubuntu	fastboot\kernel\\192.168.1.250\03-image\hisi3402\imageOS\ubunt u\ubuntu_V1.0-20250225 rootfs\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	04/03/2025 02:43 PM
910	LZ750	Bug	New	High		Ubuntu	fastboot\kernel\\192.168.1.250\03-image\hisi3402\imageOS\ubunt u\ubuntu_V1.0-20250225 rootfs\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	04/02/2025 05:18 PM
895	LZ700(LD700)	Bug	New	Urgent	PCIEM.2	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	03/27/2025 04:36 PM
894	LZ700(LD700)	Bug	New	High		Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	03/27/2025 04:36 PM
893	LZ700(LD700)	Bug	New	Urgent	1000M	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	03/27/2025 04:36 PM
850	LZ750	Bug	New	High	MICMIC	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-2 0250225	jing	02/28/2025 02:18 PM
849	LZ750	Bug	New	High	MINI PCIEM.2	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-2 0250225	jing	02/27/2025 05:15 PM
848	LZ750	Bug	New	Urgent	PCIE/	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-2 0250225	jing	02/27/2025 04:25 PM
834	LZ201	Bug	New	Normal	HDMIHDMI SPK	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/14/2025 02:42 PM
832	LZ201	Bug	New	Normal	SPK	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/13/2025 01:51 PM
831	LZ201	Bug	New	Normal	pop/rebo ot	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/13/2025 01:46 PM
827	LZ201	Bug	New	High	TP	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/08/2025 06:15 PM
826	LZ201	Bug	New	High	MIPI DSI TX mipi	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/08/2025 06:13 PM
825	LZ201	Bug	New	High	WORK	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/08/2025 11:34 AM
824	LZ201	Bug	New	Normal	eth0LED	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/06/2025 03:25 PM
786	LZ130	Bug	New	High		Ubuntu		jing	01/08/2025 05:48 PM
737	LP160	Bug	New	High	+12v24v 15v16vAHD	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\ Ubuntu	jing	01/17/2025 03:55 PM
714	LB700	Bug	New	High	U050145°C	Ubuntu	https://forum.neardi.com/d/126-hisi3403-xia-zai-gu-jian	jing	12/16/2024 06:25 PM
713	LP620	Bug	New	Urgent	USB/Type-C	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/13/2024 09:18 PM
711	LP620	Bug	New	Normal	MCP2515CAN2&3	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/13/2024 08:13 PM
710	LP620	Bug	New	Urgent	RS485 ttysWK0/ttysWK1	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/13/2024 07:55 PM

#	Project	Tracker	Status	Priority	Subject	OS	File Path	Assignee	Updated
709	LP620	Bug	New	Normal	J3304/J3303 RS485 AB	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/13/2024 07:49 PM
674	LP620	Bug	New	Normal	TF	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/12/2024 01:49 PM
666	LP620	Bug	New	Urgent	EC20 USB3.0 I/O	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/11/2024 04:51 PM
662	LP620	Bug	New	High	M.2 SSD	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/11/2024 10:05 AM
658	LP620	Bug	New	Normal		Ubuntu	Linux_for_Tegra.tar.gz	jing	12/10/2024 03:06 PM
657	LP620	Bug	New	Normal	RTC	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/10/2024 02:48 PM
642	LP160	Bug	New	Normal	A/	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	jing	01/14/2025 05:51 PM
639	LP620	Bug	New	Urgent	J3300 12V 4.84	Ubuntu	Linux_for_Tegra.tar.gz	jing	11/21/2024 04:20 PM
637	LP620	Bug	New	High	M.2 Slot M3.0	Ubuntu	Linux_for_Tegra.tar.gz	jing	11/20/2024 04:11 PM
636	LP620	Bug	New	Immediate	PCIE3.0 SSD	Ubuntu	Linux_for_Tegra.tar.gz	jing	11/20/2024 03:53 PM
609	LP122	Bug	New	Urgent	HDMI2 HDMI	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu	jing	11/15/2024 04:34 PM
601	LPM3568	Bug	New	Normal	USB2.0 USB3.0	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	jing	11/08/2024 11:41 AM
600	LPM3568	Feature	New	Normal	USB	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	jing	11/08/2024 11:55 AM
587	LP160	Bug	New	Urgent	16v AHD	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	jing	04/15/2025 05:03 PM
576	LP120	Feature	New	Urgent	FPGA	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568	jing	01/17/2025 02:06 PM
535	LP120	Feature	New	Normal		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568	jing	10/23/2024 04:31 PM
489	KD17A	Bug	New	Urgent	sdio	Ubuntu	KZ17A_ubuntu20.04_v1.8_yt8521_driver_strength_20240704.img	jing	07/16/2024 11:05 AM
472	KD16C	Bug	New	High	12V OUT 11.2V	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-v1.0.img	jing	07/01/2024 04:26 PM
433	PX30	Bug	New	Normal	KB19B		-	jing	11/14/2023 09:28 PM
422	PX30	Bug	New	Normal	ADB	Android	update-android-v8.0.1.img	jing	10/20/2023 12:53 PM