

Issues

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
953	LZ201	Bug	New	Urgent	mipi	Ubuntu	rk3576_ubuntu2204_20250429.img		05/19/2025 05:16 PM
939	LZ230	Bug	New	Normal		Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot		05/13/2025 11:33 AM
938	LZ230	Bug	New	Normal	iwconfig/lsblk/ffprobe/ftp/iperf3/at/timedatectl	Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot		05/13/2025 11:52 AM
937	LZ230	Bug	New	Normal	sudo/glmark2-es2/gst-launch-1.0		01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot		05/13/2025 11:54 AM
935	LZ230	Bug	New	Normal	FAT32	Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot		05/09/2025 05:27 PM
934	LZ230	Bug	New	High	NTFS	Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot		05/09/2025 05:27 PM
933	LZ230	Bug	New	High	arecord	Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot		05/08/2025 02:27 PM
932	LZ230	Bug	New	Normal	WiFi	Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot		05/07/2025 04:39 PM
929	LZ230	Bug	New	High	MIC1&2	Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot		04/30/2025 05:44 PM
928	LZ230	Bug	New	High	rootfs	Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot		04/30/2025 05:40 PM
885	KP12C	Bug	New	Urgent	FD7352Swift	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\kp12c\KP12C_4_1080_Ubuntu20.04_v1.0_20250117		03/17/2025 09:40 AM
884	LZ201	Bug	New	Urgent	can	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\Linux\2025_03_10		03/11/2025 04:22 PM
852	LB200	Bug	New	Urgent	type-c		\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2025_02_27\rk3576_lb200_ubuntu2204_25_02_27.img		02/28/2025 11:25 AM
851	LP201	Bug	New	High	cat /dev/ttyS3 BDGGA BDGSV	Ubuntu	ubuntu22.04_lb201_25_01_07.img		02/27/2025 06:53 PM
815	LP201	Bug	New	High	HDMI LCD	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/22/2025 10:06 AM
808	KP12C	Bug	New	High	LP120_4_1080_Ubuntu20.04_v1.0_20250110.img TF	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\pa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img		01/15/2025 05:55 PM
795	KP12C	Bug	New	Normal	AHD	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\pa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img		01/13/2025 09:55 AM
791	KP12C	Bug	New	Urgent	TF	Ubuntu	LP120_4_1080_Ubuntu20.04_v1.0_20240929.img		01/10/2025 10:33 AM
778	KP12C	Bug	New	High	AHD	Ubuntu	LP120_4_1080_Ubuntu20.04_v1.0_20240929.img		01/06/2025 09:08 PM
776	LP112	Bug	New	High	USB2.0 USB1.0	Ubuntu	LZ112_3588_ubuntu20.04_v1.0_20240204_1649		01/02/2025 02:05 PM
647	LZ130	Bug	New	Urgent	HDMI	Ubuntu			02/17/2025 05:29 PM
645	LZ130	Bug	New	Normal		Ubuntu			02/17/2025 05:33 PM
632	LB200	Bug	New	High	BT	Ubuntu	rk3576_lb200_ubuntu2204_12_03.img		02/21/2025 04:01 PM
608	LPM3568	Bug	New	Normal		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\p125\Test		11/26/2024 02:32 PM

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
606	LPM3568	Bug	New	Urgent	XXXXXXXXXXXX	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	DD	11/08/2024 06:17 PM
603	LPM3568	Bug	New	Normal	wifiXXXXXXXXHE-MCSDD	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	DD	11/08/2024 10:52 AM
598	LPM3568	Bug	New	Low	ETH1XXXXXXXX	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	DD	11/07/2024 04:07 PM
592	LP11A	Bug	New	Urgent	DDrebootXXXXXXXX	Ubuntu	LP11A_Ubuntu18.04_v3.0_20240930_Test.img	DD	11/05/2024 10:28 AM
546	LP120	Bug	New	Normal	XXXXXXXXTFDDUDDDD	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568	DD	09/05/2024 03:17 PM
471	LZ166	Bug	New	Urgent	linuxXXXXXXXXTDDDDDD	Ubuntu	update.img	DD	07/12/2024 10:18 AM