

Issues

#	Project	Tracker	Status	Priority	Subject	OS	File Path	Assignee	Updated
903	LZ201	Bug	Closed	Urgent	GPIO pin configuration	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\Linux\2025_03_10	PP	05/19/2025 10:34 AM
890	LZ210	Bug	Closed	High	LED control	Ubuntu	\\192.168.1.250\01-Public\Linx\rk3562\20250321	PP	05/09/2025 01:50 PM
888	LZ210	Bug	Closed	High	USB3.0 port not working HUB not working	Ubuntu	\\192.168.1.250\01-Public\Linx\rk3562\20250321	PP	05/09/2025 01:51 PM
887	LZ210	Bug	Closed	High	GPIO pin configuration	Ubuntu	\\192.168.1.250\01-Public\PP\rk3562\rk3562_lkd210_ubuntu22.04_12_29.img	PP	05/09/2025 01:52 PM
883	LC100	Bug	Closed	High	thermal sensor user_space		\\192.168.1.250\01-Public\wilson_test\rk3399\kernel_4_4\ddr4\LZ100X16_00_FT_LB_0508A_ddr4.img	PP	03/13/2025 11:08 AM
882	LC100	Bug	Closed	Urgent	GPIO pin configuration camera		\\192.168.1.250\01-Public\wilson_test\rk3399\kernel_4_4\ddr4\LZ100X16_00_FT_LB_0508A_ddr4.img	PP	03/13/2025 11:08 AM
881	LC100	Bug	Closed	Urgent	WiFi module	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399\kernel_4_4\ddr4\LZ100X16_00_FT_LB_0508A_ddr4.img	PP	03/13/2025 11:09 AM
880	LC100	Bug	Closed	Urgent	HDMI module	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399\kernel_4_4\ddr4\LZ100X16_00_FT_LB_0508A_ddr4.img	PP	03/13/2025 11:08 AM
839	LB200	Bug	Closed	High	SYS_STA module		\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2025_02_27\rk3576_lb200_ubuntu2204_25_02_27.img	PP	02/27/2025 06:01 PM
838	LB200	Bug	Closed	High	GPIO pin configuration iw	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2025_02_27\rk3576_lb200_ubuntu2204_25_02_27.img	PP	02/27/2025 06:01 PM
830	LZ201	Bug	Closed	High	HDMI J5600 module	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	PP	02/21/2025 04:36 PM
823	LZ201	Bug	Closed	High	BT module	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	PP	05/19/2025 11:34 AM
810	LP201	Bug	Closed	Normal	MIC module	Ubuntu	ubuntu22.04_lb201_25_01_07.img	PP	01/17/2025 03:19 PM
788	KP12C	Bug	Closed	Urgent	GPIO pin configuration	Ubuntu	LP120_4_1080_Ubuntu20.04_v1.0_20240929.img	PP	01/10/2025 09:53 PM
779	KP12C	Bug	Closed	High	HDMI_TX2 module	Ubuntu	LP120_4_1080_Ubuntu20.04_v1.0_20240929.img	PP	01/10/2025 09:53 PM
640	LPM3568	Bug	Closed	Normal	wlan module wifi	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	PP	11/25/2024 10:24 AM
631	LB200	Bug	Closed	High	J5901 module 15 pin	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu2204_11_11.img	PP	12/03/2024 05:23 PM
630	LB200	Bug	Closed	Normal	MIC module SPK module	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu2204_11_11.img	PP	12/19/2024 02:54 PM
618	LPM3568	Bug	Closed	Urgent	compatble	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	PP	11/21/2024 04:42 PM
614	LB200	Bug	Closed	Normal	GPIO pin configuration	Ubuntu	rk3576_lb200_ubuntu22.04_20241108A.img	PP	12/09/2024 09:53 AM
599	LPM3568	Bug	Closed	Normal	ETH3 module 100M	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	PP	11/11/2024 11:21 AM
573	LP120	Bug	Closed	Normal	video8 module	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp120_Ubuntu20.04_v1.0_20240929	PP	10/15/2024 10:28 AM

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
572	LP120	Bug	Closed	Normal	recovery	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\LP120_Ubuntu20.04_v1.0_20240929		10/14/2024 03:21 PM
571	LP11A	Feature	Closed	High	/mnt/60MB/s20MB/s	Ubuntu	LP11A_Ubuntu18.04_v3.0_20240930_Test.img		11/07/2024 02:06 PM
567	LP120	Bug	Closed	Urgent	AHD	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu\LPB3568_ubuntu20.04_HDMI_v1.0_20240524_1358		10/09/2024 02:16 PM
566	LP120	Bug	Closed	Normal	SH AHD	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568		10/15/2024 10:27 AM
548	LP120	Bug	Closed	Normal	iPhone	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568		09/14/2024 10:23 AM
544	LP120	Bug	Closed	High		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568		10/14/2024 04:27 PM
541	LP120	Bug	Closed	Normal	eth0Mac	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568		09/02/2024 05:12 PM
540	LP120	Bug	Closed	High		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568		09/10/2024 09:52 AM
539	LP120	Bug	Closed	High		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568		09/10/2024 09:52 AM
538	LP120	Bug	Closed	Normal		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568		09/06/2024 03:49 PM
537	LP120	Bug	Closed	High	4G	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568		09/06/2024 03:40 PM
536	LP120	Bug	Closed	Normal		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568		09/03/2024 02:31 PM
534	LP120	Bug	Closed	Normal		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568		10/14/2024 02:15 PM
533	LP120	Bug	Closed	Low	CPU_TX GND	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568		08/29/2024 03:23 PM
530	LP120	Bug	Closed	Normal	wlan0wlan1Mac	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568		09/02/2024 05:12 PM
528	LP120	Bug	Closed	High		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568		09/29/2024 02:14 PM
527	LP120	Bug	Closed	Normal	USB2.010G		\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568		09/02/2024 01:51 PM
526	LP120	Bug	Closed	Low	UBS3.0	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568		09/02/2024 02:05 PM
521	LP120	Bug	Closed	Normal	rtc	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568		10/09/2024 11:31 AM
497	LP11A	Feature	Closed	Normal	WIFI		\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V3.0\update.img		11/04/2024 05:20 PM
493	LP11A	Bug	Closed	High	Full I/O & Sys Stress	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V3.0\update.img		08/15/2024 02:43 PM
490	LP11A	Bug	Closed	Normal	Full I/O & Sys Stress Pingppp	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V3.1\update.img		07/23/2024 10:46 PM
487	LP11A	Feature	Closed	Urgent	Full I/O & Sys Stress RS485	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V3.1\update.img		07/23/2024 11:04 PM
470	LP11A	Bug	Closed	High	EMMC		\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V2.0\update.img		07/01/2024 08:15 PM
468	LP11A	Bug	Closed	Normal	Cam 1~4 90°	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\update.img		07/12/2024 11:30 AM
463	LP11A	Bug	Closed	Normal	LP11A	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V1.0\update.img		07/15/2024 09:09 PM

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
461	LP11A	Bug	Closed	Urgent	IMU	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V1.0\update.img		07/23/2024 10:56 PM
458	LP11A	Bug	Closed	Normal	CAN	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V1.0\update.img		06/13/2024 11:11 AM
455	LP11A	Bug	Closed	Normal	MAC	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V1.0\update.img		07/18/2024 03:45 PM
454	LP11A	Bug	Closed	Normal	rockchip-vop ff900000.vop: [drm:vop_isr] *ERROR* POST_BUF_EMPTY irq err	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V1.0\update.img		06/13/2024 03:09 PM
453	LP11A	Bug	Closed	Low		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V1.0\update.img		07/23/2024 11:05 PM