

Issues

#	Project	Tracker	Status	Priority	Subject	OS	File Path	Assignee	Updated
792	LP201	Bug	New	High	LCD display issue	Ubuntu	ubuntu22.04_lb201_25_01_07.img	er	01/09/2025 10:04 AM
790	LP201	Bug	New	High	Keyboard not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img	er	01/08/2025 08:02 PM
789	LP201	Bug	New	High	RS485/CAN communication	Ubuntu	ubuntu22.04_lb201_25_01_07.img	er	01/08/2025 07:57 PM
787	LP201	Bug	New	Urgent	Power supply issue 3-5V	Ubuntu	ubuntu22.04_lb201_25_01_07.img	er	01/22/2025 10:42 AM
785	LP201	Bug	New	Immediate	Wi-Fi connectivity	Ubuntu	ubuntu22.04_lb201_25_01_07.img	er	01/08/2025 06:19 PM
782	LP201	Bug	New	High	eth1 network interface	Ubuntu	ubuntu22.04_lb201_25_01_07.img	er	02/26/2025 03:49 PM
781	LP201	Bug	New	High	DC/IN pins	Ubuntu	ubuntu22.04_lb201_25_01_07.img	er	01/08/2025 11:32 AM
725	LB200	Bug	Closed	High	PCBA components			er	02/21/2025 03:42 PM
723	LB200	Bug	Closed	High	U4101 component			er	02/21/2025 03:41 PM
633	LB200	Bug	Closed	High	Power supply 2.6v	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	er	02/17/2025 02:23 PM
628	LB200	Bug	Closed	Normal	USB3.0 port	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	er	02/18/2025 02:22 PM
627	LB200	Bug	New	Normal	J2800 USB connector	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu2204_11_11.img	er	11/14/2024 03:19 PM
626	LB200	Bug	Closed	Urgent	6-pin connector	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	er	02/21/2025 03:44 PM
625	LB200	Bug	New	Normal	Type-C port	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu2204_11_11.img	er	12/04/2024 04:48 PM
624	LB200	Bug	New	Normal	Type-C debug	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu2204_11_11.img	er	12/04/2024 04:48 PM
623	LB200	Bug	New	Urgent	5G module	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu2204_11_11.img	er	12/09/2024 10:15 AM
622	LB200	Bug	Closed	Immediate	MINI PCI component	Ubuntu		er	02/21/2025 03:50 PM
620	LB200	Bug	New	High	Display issue	Ubuntu	rk3576_lb200_ubuntu22.04_20241108A.img	er	12/06/2024 04:59 PM
619	LB200	Bug	New	Normal	J4500/J4501 pins	Ubuntu	rk3576_lb200_ubuntu22.04_20241108A.img	er	11/13/2024 09:09 PM
616	LB200	Bug	Closed	High	Power supply / gpio	Ubuntu	rk3576_lb200_ubuntu22.04_20241108A.img	er	02/18/2025 03:07 PM
525	LP11A	Bug	New	Normal	ESD -8KV 485/gpio		-	er	10/30/2024 04:44 PM