

Issues

#	Project	Tracker	Status	Priority	Subject	OS	Image	Assignee	Updated
556	WIFI	Bug	New	Urgent	FD7352S,STA 5G/2.4G mcs	Ubuntu	update-sdio.img	KuangJie	09/14/2024 02:28 PM
555	WIFI	Bug	New	Urgent	FD7352S/P AP AP SSID 1 2	Ubuntu	update-sdio.img	KuangJie	12/18/2024 07:30 PM
553	WIFI	Bug	New	High	FD7352P STA 2.4G ax-40 tx mcs 11 mcs 11 mcs	Ubuntu	update-pcie.img	KuangJie	09/12/2024 01:45 PM
552	WIFI	Bug	New	High	FD7352P STA ac-80 iperf3	Ubuntu	update-pcie.img	KuangJie	09/12/2024 10:31 AM
551	WIFI	Bug	New	High	AP6275S LPA3588 AP 70%	Ubuntu	update.img	sun	09/11/2024 06:42 PM
550	WIFI	Bug	New	High	FD7352P,STA 2.4G n only rx ac. n ac	Ubuntu	update-pcie.img	KuangJie	09/10/2024 04:59 PM
549	WIFI	Bug	New	High	FD7352P, ax80 tx 70. 800~900Mbps/sec 750 Mbps/sec	Ubuntu	update-pcie.img	KuangJie	09/12/2024 01:48 PM
492	KD17A	Bug	New	High	KD17A, iperf3 100M bits/sec . 500-600Mbps/sec	Ubuntu	KZ17A_ubuntu20.04_v1.9_fixed_fd7352s_crash_20240708.img	sun	07/17/2024 02:16 PM
489	KD17A	Bug	New	Urgent	sdio	Ubuntu	KZ17A_ubuntu20.04_v1.8_yt8521_driver_strength_20240704.img	jing	07/16/2024 11:05 AM
471	LZ166	Bug	New	Urgent	linux T	Ubuntu	update.img		07/12/2024 10:18 AM
435	KD17A	Bug	New	High	KD17A AP SSID, WIFI	Ubuntu	update.img	sun	03/12/2024 03:11 PM
354	LB170	Bug	New	Normal	LB170, M.2	Ubuntu	lb170_3588_ubuntu20.04_v1.0_20230607_1025.img	sun	06/27/2023 10:51 AM