

Issues

#	Project	Tracker	Status	Priority	Subject	OS	Details	Assignee	Updated
977	LZ750	Bug	New	High	摄像头CAM1/CAM2/OS04A10	Ubuntu	ubuntu22.04_V1.3_2G_DDR_OS_1.5G-20250606	sun	06/18/2025 03:03 PM
976	LZ750	Bug	New	High	UART4/dev/ttyAMA4	Ubuntu	ubuntu22.04_V1.3_2G_DDR_OS_1.5G-20250606	sun	06/18/2025 02:04 PM
975	LZ750	Bug	New	High	UART2/dev/ttyAMA2	Ubuntu	ubuntu22.04_V1.3_2G_DDR_OS_1.5G-20250606	sun	06/18/2025 01:51 PM
974	LZ750	Bug	New	High	wifi(wlan0),wifi	Ubuntu	ubuntu22.04_V1.3_2G_DDR_OS_1.5G-20250606	sun	06/18/2025 01:54 PM
973	LZ750	Bug	New	High	以太网(eth0),以太网	Ubuntu	ubuntu22.04_V1.3_2G_DDR_OS_1.5G-20250606	sun	06/18/2025 11:21 AM
972	LZ750	Bug	New	High	RTC time	Ubuntu	ubuntu22.04_V1.3_2G_DDR_OS_1.5G-20250606	sun	06/18/2025 11:16 AM
971	LZ750	Bug	New	High	485/dev/ttyAMA1	Ubuntu	ubuntu22.04_V1.3_2G_DDR_OS_1.5G-20250606	sun	06/18/2025 11:03 AM
970	LZ700(LD700)	Bug	New	Normal	TF	Ubuntu	ubuntu_V1.4-support-8G-DDR-UI-20250416	sun	06/17/2025 05:12 PM
952	LZ750	Bug	New	High	thermal/dmccpufreq	Ubuntu	fastboot\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.1-20250515; kernel:\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.1-20241218\kernel; rootfs:\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.1-20241218\rootfs	sun	05/19/2025 03:25 PM
945	LB700	Bug	New	Normal		Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.4-support-8G-DDR-UI-20250416	sun	05/13/2025 11:41 AM
941	LB700	Bug	New	Normal	TF	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.4-support-8G-DDR-UI-20250416	sun	05/12/2025 02:47 PM
940	LZ750	Bug	New	Normal	DDR	Ubuntu		sun	05/12/2025 01:44 PM
921	LZ750	Bug	New	Urgent	1000M	Ubuntu	fastboot\\kernel\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	04/03/2025 02:59 PM
920	LZ750	Bug	New	High	audio/demo	Ubuntu	fastboot\\kernel\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/03/2025 02:57 PM
919	LZ750	Bug	New	Urgent	gpio50	Ubuntu	fastboot\\kernel\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	04/03/2025 02:43 PM
918	LZ750	Bug	New	Urgent	USB100Msshcamer	Ubuntu	fastboot\\kernel\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	04/03/2025 02:28 PM
917	LZ750	Bug	New	High	IP	Ubuntu	fastboot\\kernel\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/02/2025 06:18 PM
915	LZ750	Bug	New	High	neardi		fastboot\\kernel\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	04/08/2025 06:20 PM
914	LZ750	Bug	New	Urgent	Out of memory		fastboot\\kernel\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	06/09/2025 09:55 AM
913	LZ750	Bug	New	High	J2600--normal		fastboot\\kernel\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	04/02/2025 05:29 PM

#	Project	Tracker	Status	Priority	Subject			Assignee	Updated
912	LZ750	Bug	New	High	J2903--TP		fastboot\kernel\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	04/02/2025 05:28 PM
911	LZ750	Bug	New	High	J2904--30pin FPC		fastboot\kernel\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	04/02/2025 05:25 PM
910	LZ750	Bug	New	High		Ubuntu	fastboot\kernel\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	04/02/2025 05:18 PM
909	LZ750	Bug	New	Urgent	ddr	Ubuntu	fastboot\kernel\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/02/2025 05:38 PM
904	LZ700(LD700)	Bug	New	Normal	Neardi		ubuntu_V1.4-support-8G-DDR-UI-20250416	Linx	06/17/2025 05:24 PM
902	LZ700(LD700)	Bug	New	High	camera	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/01/2025 03:36 PM
901	LZ700(LD700)	Bug	New	High	USB100Msshcamera	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/01/2025 03:33 PM
900	LZ700(LD700)	Bug	New	High	audiodemoaudio	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	03/27/2025 05:30 PM
899	LZ700(LD700)	Bug	New	High	J2904--30pin FPC	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	03/27/2025 04:57 PM
898	LZ700(LD700)	Bug	New	High	J2903--TP	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	03/27/2025 04:46 PM
897	LZ700(LD700)	Bug	New	High	J2600--normal	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	03/27/2025 04:42 PM
896	LZ700(LD700)	Bug	New	High	npudemoNPU	Ubuntu	ubuntu_V1.4-support-8G-DDR-UI-20250416	Linx	06/17/2025 05:25 PM
895	LZ700(LD700)	Bug	New	Urgent	PCIEM.2	Ubuntu	ubuntu_V1.4-support-8G-DDR-UI-20250416	jing	06/17/2025 04:27 PM
894	LZ700(LD700)	Bug	New	High		Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	03/27/2025 04:36 PM
893	LZ700(LD700)	Bug	New	Urgent	1000M	Ubuntu	ubuntu_V1.4-support-8G-DDR-UI-20250416	jing	06/17/2025 04:25 PM
879	LB700	Bug	New	High	HDMI	Ubuntu	192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250314	Linx	03/14/2025 03:26 PM
874	LB700	Bug	New	High	J2904--30pin FPC	Ubuntu	192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304		03/06/2025 03:19 PM
872	LB700	Bug	New	Normal	camerademo	Ubuntu	192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	04/18/2025 06:37 PM
871	LB700	Bug	New	High	Neardi	Ubuntu	192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/07/2025 05:23 PM

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
852	LB200	Bug	New	Urgent	type-c		\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2025_02_27\rk3576_lb200_ubuntu2204_25_02_27.img		02/28/2025 11:25 AM
845	LB200	Bug	New	High	USB3.0HUB	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	Linx	02/27/2025 03:25 PM
840	LB200	Bug	New	Normal	mmcb1k0mmcb1k1	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	Linx	02/18/2025 05:20 PM
837	LB200	Bug	New	Urgent	USB3.03.0		\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	yuncai	02/18/2025 02:23 PM
836	LB200	Bug	New	Normal			\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	Linx	02/17/2025 03:31 PM
835	Wifi_Factory_Test	Bug	New	Normal	WiFi-WiFi				02/14/2025 04:11 PM
807	Wifi_Factory_Test	Bug	New	Urgent	Wifi				02/14/2025 04:15 PM
806	Wifi_Factory_Test	Bug	New	High					01/15/2025 03:45 PM
805	Wifi_Factory_Test	Bug	New	Normal	Wifi				01/15/2025 03:42 PM
804	Wifi_Factory_Test	Bug	New	Normal	XWGageBUGXW				01/15/2025 04:30 PM
803	Wifi_Factory_Test	Bug	New	High	wifi1m				01/15/2025 03:32 PM
802	Wifi_Factory_Test	Bug	New	Normal	wifi				01/15/2025 03:28 PM
801	Wifi_Factory_Test	Bug	New	Urgent	Wifi				01/15/2025 03:26 PM
800	Wifi_Factory_Test	Bug	New	High	Wifi				02/06/2025 10:24 AM
799	Wifi_Factory_Test	Bug	New	Normal	Wifi				01/15/2025 03:18 PM
749	LB700	Bug	New	High		Ubuntu		shiliang	12/23/2024 04:05 PM
747	LB700	Bug	New	High	4	Ubuntu		shiliang	12/23/2024 02:34 PM
746	LB700	Bug	New	Normal		Ubuntu		shiliang	12/23/2024 02:27 PM
745	LB700	Bug	New	High		Ubuntu		shiliang	12/23/2024 02:24 PM
734	LB700	Bug	New	High	demo	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/07/2025 05:24 PM
724	LB200	Bug	New	Normal					02/17/2025 01:48 PM
721	LB200	Bug	New	High		Ubuntu			02/17/2025 01:56 PM

#	Project	Tracker	Status	Priority	Subject	OS	OS Path	Assignee	Updated
719	LB200	Bug	New	High	XXXXXXXXXXXX			xxx	02/17/2025 01:56 PM
717	LB700	Bug	New	High	XXXXthermalXdmccpufreq	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	sun	03/07/2025 02:44 PM
714	LB700	Bug	New	High	U0501XXXXXXXX45°C	Ubuntu	https://forum.neardi.com/d/126-hisi3403-xia-zai-gu-jian	jing	12/16/2024 06:25 PM
700	LB700	Bug	New	Normal	J2500XXXX	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	shiliang	03/06/2025 03:20 PM
699	LB700	Bug	New	High	J2903--TPXXXXXXXX	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	sun	03/06/2025 03:25 PM
690	LB700	Bug	New	Normal	Mini-PCIEXXXX1808	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	sun	03/17/2025 11:04 AM
689	LB700	Bug	New	Normal	Mini-PCIEXXXXXXXX	Ubuntu	https://forum.neardi.com/d/126-hisi3403-xia-zai-gu-jian	shiliang	12/13/2024 10:41 AM
682	LB700	Bug	New	Urgent	LB700--XX--XXXXXXXXLinuxXXXXXXXXXXXXubuntuXX	Ubuntu	https://forum.neardi.com/d/126-hisi3403-xia-zai-gu-jian	sun	12/18/2024 05:36 PM
677	LB700	Bug	New	Urgent	LB700--XXXX--XXXXXXXXXXXXXXXXXXXXXX XXXX	Ubuntu		sun	03/07/2025 05:25 PM
571	LP11A	Bug	New	High	/mnt/XXXXXXXX60MB/sXXXX20MB/sXX	Ubuntu	LP11A_Ubuntu18.04_v3.0_20240930_Test.img	jing	05/26/2025 07:01 PM
570	KZ117	Bug	New	High	macXXXXXXXXmacXXXXXXIPXXXXXXXX	Ubuntu	rk3399pro_KZ117_ubuntu_gaussian_ddr3_20240628.img	Linx	11/25/2024 03:32 PM
562	KD16C(XXX)	Bug	New	Normal	wifi_XXpingXwaln0XXXXpingXwifiXXXXIPX X	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240806v2.0.img		09/23/2024 11:30 AM
517	KD16C(XXX)	Bug	New	High	XXXX_X_Y_XXXXXXXXXXXXXXXXXXXX	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240806v2.0.img	xxx	08/13/2024 03:14 PM
514	LP11A	Bug	New	Normal	XXXXXXXXXX_XXXXXX			X	08/27/2024 10:22 AM
508	KD16C(XXX)	Bug	New	Normal	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240702v1.0.img		08/07/2024 10:40 AM
500	KD16C(XXX)	Bug	New	High	SIMXXXXXXXXXXXX	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240702v1.0.img	xxx	07/24/2024 11:50 AM
496	LCS3588(LC166)	Bug	New	Normal	XXgpioXXXXXX	Ubuntu	lkd3588-t0-ubuntu-240718.img	sun	07/22/2024 11:30 AM
494	LP11A	Feature	New	Low	-20XXXXXXXX4XAHDXXXX_KP11A	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V3.2	Linx	11/07/2024 02:05 PM
486	LP160	Bug	New	Normal	LKD3588_Debian_UXXXXXXXX	Debian		Linx	07/15/2024 07:06 PM
483	LCS3588(LC166)	Bug	New	Normal	XXXXXXXXXXXXXXXXXXXX	Ubuntu	lkd3588-t0-ubuntu-240703.img	sun	07/10/2024 06:09 PM
482	LCS3588(LC166)	Bug	New	High	LVDSXXXXXXLD166XXXXXXXXLVDSXX	Ubuntu	lkd3588-t0-ubuntu-240703.img	sun	07/10/2024 04:08 PM
481	LCS3588(LC166)	Bug	New	Normal	btXXXX	Ubuntu	lkd3588-t0-ubuntu-240703.img	sun	07/10/2024 04:08 PM

#	Project	Tracker	Status	Priority	Subject	OS	Image	Assignee	Updated
480	LCS3588(LC166)	Bug	New	Normal	wifi问题	Ubuntu	lkd3588-t0-ubuntu-240703.img	sun	07/10/2024 04:07 PM
476	KD16C()	Bug	New	High	USB1_3.0U2.03.0	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240702v1.0.img	shiliang	07/08/2024 06:18 PM
472	KD16C()	Bug	New	High	12V OUT11.2V	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-v1.0.img	jing	07/01/2024 04:26 PM
464	KZ16E	Bug	New	High	M.2	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\pcie3.0\LKD3588_ubuntu20.04_v1.0_20240523_1544.img	sun	06/14/2024 02:33 PM
439	LB120	Bug	New	High	LB120eth1350	Ubuntu	LBA3568_ubuntu20.04_v1.0_20240301_2020.img	Linx	03/29/2024 10:58 AM
434	LP122	Bug	New	Urgent	5G(RM500U-CNV)	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230801_1621.img	Linx	09/25/2024 04:23 PM
432	LP160	Bug	New	Normal	CANloopback	Ubuntu		sun	11/08/2023 05:37 PM
420	LP160	Bug	New	Urgent	LPA358812H	Ubuntu		sun	10/17/2023 09:49 AM
419	LP160	Bug	New	Urgent	358840-50ms100ms	Ubuntu		Linx	10/16/2023 11:27 AM
418	LP160	Bug	New	Urgent	LPA3588	Ubuntu		sun	10/16/2023 11:23 AM
408	LP160	Bug	New	High	sony1.mp4 ch-test.wav	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/13/2023 11:49 AM
407	LP160	Bug	New	High	HDMI_OUT3	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/13/2023 10:06 AM
406	LP162	Bug	New	High	sony1.mp4 ch-test.wav	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/11/2023 05:46 PM
388	LP162	Feature	New	High	can3588	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/26/2023 02:44 PM
380	LP122	Bug	New	High	RS232--COM3tysWK3	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	sun	07/10/2023 11:57 AM
376	LP122	Bug	New	Normal	rockchip-test/npurknn_demo.sh npufreq_scaling.sh	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	Linx	11/14/2023 04:02 PM
372	LP122	Bug	New	High	HDMI-RXvideo1	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	sun	07/04/2023 11:49 AM
370	LP160	Bug	New	Normal	USBtype-cUSB	Android	LZ160_3588_Android12_v1.0_20230629.img	sun	07/03/2023 03:42 PM
367	LP122	Bug	New	Normal	SDSD	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	sun	06/30/2023 05:50 PM
366	LP122	Bug	New	Normal	UnixBenchGlmark2-es2Stream	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	Linx	11/14/2023 03:26 PM
365	LP122	Bug	New	Normal	A/INI23450mV	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	sun	06/30/2023 05:50 PM
342	LP112	Bug	New	Normal	usb3.03.0U	Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704		07/03/2023 11:33 AM
339	LP112	Bug	New	Normal		Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704	Linx	07/18/2023 04:25 PM

#	Project	Tracker	Status	Priority	Subject	OS	Device	Assignee	Updated
338	LP112	Bug	New	High	Audio output distortion when playing high frequency signals	Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704	Linx	07/14/2023 10:35 AM
337	LP112	Bug	New	High	Audio output distortion when playing high frequency signals	Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704		07/18/2023 04:22 PM
334	LP162	Bug	New	Normal	HDMI-OUT3 audio output distortion when playing high frequency signals	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/11/2023 06:16 PM
331	LP162	Bug	New	Normal	Audio output distortion when playing high frequency signals	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	sun	05/12/2025 11:56 AM
330	LP162	Bug	New	Normal	Audio output distortion when playing high frequency signals	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/11/2023 03:49 PM
329	LP162	Bug	New	Normal	Audio output distortion when playing high frequency signals	Ubuntu	RK3588_UBUNTU_V1_230519.img	sun	06/09/2023 05:49 PM
328	LP162	Bug	New	Normal	Audio output distortion when playing high frequency signals	Ubuntu	RK3588_UBUNTU_V1_230519.img	sun	06/09/2023 05:47 PM
327	LP162	Bug	New	Normal	Audio output distortion when playing high frequency signals	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/11/2023 03:57 PM
326	LP162	Bug	New	Normal	Audio output distortion when playing high frequency signals	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/11/2023 03:58 PM
323	LP162	Bug	New	Normal	Audio output distortion when playing high frequency signals	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/11/2023 03:29 PM
319	LP162	Bug	New	High	Audio output distortion when playing high frequency signals	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/18/2023 03:40 PM
316	LP160	Bug	New	Normal	LPA3588 Ubuntu 20.04.5 HDMI-OUT3 audio output distortion when playing high frequency signals	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/13/2023 10:14 AM
311	LP160	Bug	New	Normal	LPA3588 Ubuntu 20.04.5 M.2 audio output distortion when playing high frequency signals	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/13/2023 03:44 PM
310	LP160	Bug	New	Normal	LPA3588 Ubuntu 20.04.5 A/I audio output distortion when playing high frequency signals	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/12/2023 04:45 PM
309	LP160	Bug	New	Normal	LPA3588 Ubuntu 20.04.5 A/I audio output distortion when playing high frequency signals	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/12/2023 04:42 PM
305	LP160	Bug	New	Normal	LPA3588 Ubuntu 20.04.5 BT audio output distortion when playing high frequency signals	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	01/14/2025 06:32 PM
291	LP160	Bug	New	Normal	LPA3588 Ubuntu 20.04.5 audio output distortion when playing high frequency signals	Ubuntu	LP160XXX03_FT_UBUNTU_F6_V1_230509.img	sun	05/18/2023 04:45 PM
288	LP160	Bug	New	Normal	LPA3588 Ubuntu 20.04.5 audio output distortion when playing high frequency signals	Ubuntu	LP160XXX03_FT_UBUNTU_F6_V1_230509.img	sun	05/18/2023 04:36 PM
286	LP160	Bug	New	Normal	LPA3588 Ubuntu 20.04.5 audio output distortion when playing high frequency signals	Ubuntu	LP160XXX03_FT_UBUNTU_F6_V1_230509.img	Linx	06/06/2023 11:39 AM

#	Project	Tracker	Status	Priority	Subject	OS	Image	Assignee	Updated
284	LP160	Bug	New	Normal	LPA3588_Ubuntu 20.04.5_ DP_000000000000	Ubuntu	LP160XXX03_FT_UBUNTU_F6_V1_230509.img	sun	05/18/2023 04:08 PM
283	LP160	Bug	New	Normal	LPA3588_Ubuntu 20.04.5_ HDMI_000000000000	Ubuntu	LP160XXX03_FT_UBUNTU_F6_V1_230509.img	sun	05/18/2023 03:43 PM
282	LP160	Bug	New	Normal	LPA3588_Ubuntu 20.04.5_ HDMI_00_HDMI--OUT3_000000000000	Ubuntu	LP160XXX03_FT_UBUNTU_F6_V1_230509.img	sun	05/18/2023 03:35 PM