

Issues

#	Project	Tracker	Status	Priority	Subject	OS	File Path	Assignee	Updated
923	LZ210	Bug	New	Urgent	sudo -i 无法进入cpu	Ubuntu	rk3562_ubuntu2204_20250409A.img	Linx	04/25/2025 11:01 AM
907	LZ210	Bug	New	Urgent	usb3.0hub 无法识别设备	Ubuntu	\\192.168.1.250\01-Public\Linx\rk3562\20250321	Linx	04/01/2025 09:46 AM
903	LZ201	Bug	New	Urgent	无法识别设备	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\Linux\2025_03_10	Linx	03/31/2025 09:42 AM
890	LZ210	Bug	New	High	LED 无法点亮	Ubuntu	\\192.168.1.250\01-Public\Linx\rk3562\20250321	Linx	03/21/2025 06:54 PM
889	LZ210	Bug	Closed	High	usb2.0 无法识别usb3.0 设备	Ubuntu	\\192.168.1.250\01-Public\Linx\rk3562\20250321	Linx	03/31/2025 05:17 PM
888	LZ210	Bug	New	High	USB3.0 无法识别HUB 设备HUB 无法识别U 盘2.0 无法识别1.0 盘	Ubuntu	\\192.168.1.250\01-Public\Linx\rk3562\20250321	Linx	03/21/2025 06:27 PM
887	LZ210	Bug	New	High	无法识别设备	Ubuntu	\\192.168.1.250\01-Public\Linx\rk3562\rk3562_lkd210_ubuntu22.04_12_29.img	Linx	03/20/2025 06:48 PM
885	KP12C	Bug	New	Urgent	无法识别设备FD7352Swifi	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\kp12c\KP12C_4_1080_Ubuntu20.04_v1.0_20250117	Linx	03/17/2025 09:40 AM
884	LZ201	Bug	New	Urgent	can 无法识别设备can 无法识别设备can 无法识别设备can 无法识别设备	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\Linux\2025_03_10	Linx	03/11/2025 04:22 PM
870	LZ201	Bug	New	Urgent	ubuntu 无法识别设备sync 无法识别设备emmc 无法识别设备	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\Linux\2025-01-23	Linx	03/05/2025 06:21 PM
857	LP201	Bug	New	High	RTC 无法识别设备	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	03/03/2025 04:04 PM
856	LZ750	Bug	Closed	High	MIPI LCD 无法识别 Touch Screen Slot	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	jing	04/02/2025 05:30 PM
855	LZ750	Bug	New	High	无法识别设备	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	sun	02/28/2025 02:14 PM
854	LZ750	Bug	New	Normal	无法识别设备	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	Linx	02/28/2025 02:23 PM
853	LZ750	Bug	Closed	High	GPIO_101 无法识别设备1.8V 无法识别设备	Ubuntu	fastboot kernel \\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs \\192.168.1.250\01-Public\Linx\hisi3403\ubuntu\20250326	sun	04/03/2025 02:54 PM
851	LP201	Bug	New	High	无法识别设备cat /dev/ttyS3 无法识别设备BDGGA 无法识别设备BDGSV	Ubuntu	ubuntu22.04_lb201_25_01_07.img	Linx	02/27/2025 06:53 PM
850	LZ750	Bug	New	High	MIC 无法识别设备MIC 无法识别设备	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	jing	02/28/2025 02:18 PM
849	LZ750	Bug	New	High	无法识别设备MINI PCIE 无法识别设备M.2	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	jing	02/27/2025 05:15 PM
848	LZ750	Bug	New	Urgent	无法识别设备PCIE 无法识别设备	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	jing	02/27/2025 04:25 PM

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
847	LZ750	Bug	New	High	5G	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	sun	02/28/2025 02:17 PM
844	LB700	Bug	New	High	audio demo audio	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	04/18/2025 06:38 PM
843	LB700	Bug	Closed	High	camera J3504	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/06/2025 01:53 PM
842	LB700	Bug	Closed	Urgent	camera	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250314	Linx	04/18/2025 06:35 PM
841	LB700	Bug	Closed	Immediate	rootfs_20250219A	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu	Linx	03/06/2025 03:13 PM
834	LZ201	Bug	New	Normal	HDMI HDMI SPK	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/14/2025 02:42 PM
833	LZ201	Bug	New	Normal	4g etho 4g DNS	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	Linx	02/13/2025 05:58 PM
832	LZ201	Bug	New	Normal	SPK	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/13/2025 01:51 PM
831	LZ201	Bug	New	Normal	pop / reboot	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/13/2025 01:46 PM
830	LZ201	Bug	Closed	High	HDMI J5600	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23		02/21/2025 04:36 PM
829	LZ201	Bug	New	Normal	HDMI type-c DP HDMI	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	Linx	02/10/2025 02:08 PM
828	LZ201	Bug	New	Low	4.78GB 4GB	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	Linx	02/10/2025 04:08 PM
827	LZ201	Bug	New	High	TP	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/08/2025 06:15 PM
826	LZ201	Bug	New	High	MIPI DSI TX mipi	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/08/2025 06:13 PM
825	LZ201	Bug	New	High	WORK	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/08/2025 11:34 AM
824	LZ201	Bug	New	Normal	etho LED	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/06/2025 03:25 PM
823	LZ201	Bug	New	High	BT	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23		02/06/2025 02:57 PM
822	LZ201	Bug	New	Normal	root gst-launch-1.0	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	Linx	02/06/2025 02:00 PM
821	LZ201	Bug	New	Urgent	MIPI 3A	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	Linx	02/06/2025 01:40 PM
819	LP201	Bug	New	Normal	2280M.2	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/23/2025 09:52 AM
818	LP201	Bug	New	High	HDMI FPC	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/22/2025 12:00 PM
817	LP201	Bug	New	High	SIM SIM	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/22/2025 10:56 AM
816	LP201	Bug	New	High	rootfs NetworkManager-wait-online.service 27.848s	Ubuntu	ubuntu22.04_lb201_25_01_07.img	Linx	01/22/2025 11:46 AM
815	LP201	Bug	New	High	HDMI LCD HDMI	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/22/2025 10:06 AM
814	LP201	Bug	New	Normal	ubuntu debian 1080P30 1080P60 buildroot	Ubuntu	ubuntu22.04_lb201_25_01_07.img	Linx	01/21/2025 04:23 PM
813	LP201	Bug	New	High	D/I GPIO55	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/21/2025 03:56 PM

#	Project	Tracker	Status	Priority	Subject	OS	Image	Assignee	Updated
812	LP201	Bug	New	High	D/O 12V	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/21/2025 10:54 AM
811	LP201	Bug	New	Normal	reboot--SPK	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/22/2025 11:01 AM
810	LP201	Bug	Closed	Normal	MIC	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/17/2025 03:19 PM
809	LP201	Bug	New	High	Type-C	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/16/2025 05:56 PM
808	KP12C	Bug	New	High	LP120_4_1080_Ubuntu20.04_v1.0_20250110.img TF	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img		01/15/2025 05:55 PM
796	KP12C	Bug	New	Normal	usb2.0 usb3.0 hub 30%	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img	Linx	01/14/2025 11:54 AM
792	LP201	Bug	New	High	LCD	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/09/2025 10:04 AM
790	LP201	Bug	New	High		Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/08/2025 08:02 PM
789	LP201	Bug	New	High	RS485/CAN	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/08/2025 07:57 PM
787	LP201	Bug	New	Urgent	3-5	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/22/2025 10:42 AM
786	LZ130	Bug	New	High		Ubuntu		jing	01/08/2025 05:48 PM
785	LP201	Bug	New	Immediate		Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/08/2025 06:19 PM
782	LP201	Bug	New	High	eth1	Ubuntu	ubuntu22.04_lb201_25_01_07.img		02/26/2025 03:49 PM
781	LP201	Bug	New	High	DC/IN	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/08/2025 11:32 AM
780	LZ210	Bug	New	Low	C2045 J9200	Ubuntu	rk3562_lkd210_ubuntu22.04_12_29.img	zenghui	01/08/2025 10:47 AM
776	LP112	Bug	New	High	USB2.0 USB1.0	Ubuntu	LZ112_3588_ubuntu20.04_v1.0_20240204_1649		01/02/2025 02:05 PM
774	LZ210	Bug	New	High	SARADC0_IN6 1.8V GND 1.3V	Ubuntu	rk3562_lkd210_ubuntu22.04_12_29.img	zenghui	01/06/2025 11:14 AM
772	LZ210	Bug	New	High	WIFI/BT	Ubuntu	rk3562_lkd210_ubuntu22.04_12_29.img		12/30/2024 10:44 AM
771	LZ210	Bug	New	High		Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/27/2024 09:06 PM
770	LZ210	Bug	New	Normal	ADC_IN voltage_raw	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/27/2024 05:44 PM
769	LZ210	Bug	New	Urgent	ADC_IN 0.1V	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/27/2024 05:46 PM
767	LZ210	Bug	New	Normal	reboot log	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img		12/26/2024 04:34 PM
766	LZ210	Bug	New	High	Ubuntu --	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	12/26/2024 04:31 PM
765	LZ210	Bug	New	High	CPU GPU NPU	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img		01/03/2025 05:48 PM
763	LZ210	Bug	New	Normal	4k	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	12/25/2024 08:18 PM
762	LZ210	Bug	Closed	High	EMMC	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img		01/03/2025 06:09 PM

#	Project	Tracker	Status	Priority	Subject	OS	Image	Assignee	Updated
755	LZ210	Bug	Closed	Normal	usb2.0	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img		01/03/2025 06:10 PM
754	LZ210	Bug	New	High	USB3.0_OTG	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img		01/13/2025 09:53 AM
750	LZ210	Bug	Closed	Normal	WIFI/BT	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img		01/03/2025 06:15 PM
748	LZ210	Bug	New	High	root	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	01/10/2025 10:15 AM
744	LZ210	Bug	Closed	Low	HDMI	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img		01/03/2025 06:18 PM
743	LZ210	Bug	New	Urgent	MIPI	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img		12/31/2024 02:10 PM
742	LZ210	Bug	New	High	POP	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/24/2024 04:53 PM
741	LZ210	Bug	Closed	Normal	SDDiskTool_v1.64	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img		01/03/2025 06:26 PM
738	LZ210	Bug	New	High	LC210	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img		12/20/2024 04:24 PM
736	LZ210	Bug	New	High	USB2.0_4G	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/24/2024 04:55 PM
735	LZ210	Bug	Closed	Immediate	SIM	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img		01/03/2025 06:43 PM
733	LZ210	Bug	New	Normal		Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	12/31/2024 04:23 PM
731	LZ210	Bug	New	High	power	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	01/06/2025 11:18 AM
730	LZ210	Bug	New	Normal	Recovery	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img		01/03/2025 06:44 PM
729	LZ210	Bug	New	Immediate		Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/25/2024 02:49 PM
728	LZ210	Bug	New	High	power	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	01/03/2025 06:52 PM
727	LZ210	Bug	New	Low	system LED	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/25/2024 03:10 PM
726	LZ210	Bug	New	High	system LED	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img		01/03/2025 06:54 PM
720	LZ210	Bug	New	Urgent		Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/25/2024 02:59 PM
718	LZ210	Bug	New	Low	4.77 GB	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img		12/31/2024 02:20 PM
702	LZ210	Bug	New	Normal	Ethernet	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/25/2024 03:00 PM
672	LZ210	Bug	Closed	Normal	USB2.0	Ubuntu	rk3562_lkd210_ubuntu2004.img	zenghui	12/25/2024 02:58 PM
671	LZ210	Bug	New	Immediate	emmc	Ubuntu	rk3562_lkd210_ubuntu2004.img		01/03/2025 06:57 PM
644	LP11A	Bug	New	Normal	USB2.0	Debian	LZ210V1.0	mike	12/02/2024 05:51 PM