

Ubuntu_22.04 - Bug #1016

LPA3588_Vout_12V

07/02/2025 05:15 PM - mike

Status: New Priority: Normal Assignee: jing Category: Target version: : LP160 CPU: RK3588 : LPA3588 / : 05 : 01 / : 05 : LPA3588_ubuntu22.04_v1.0_20250415_1601.img : Ubuntu	Start date: 07/02/2025 Due date: % Done: 0% Estimated time: 0.00 hour Spent time: 0.00 hour : Linux LPA3588 6.1.84 #1 SMP Wed Apr 9 11:21:26 CST 2025 aarch64 aarch64 aarch64 GNU/Linux APP : - : 100% : FD7352S : YT8521SC EMMC : - : lnustry I&O
Description 9V 8.64V	