

Ubuntu_22.04 - Bug #1018

LPA3588_ETH1_ETH2_MAC

07/02/2025 06:32 PM - mike

Status:	New	Start date:	07/02/2025
Priority:	Urgent	Due date:	
Assignee:	Linx	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LP160	:	Linux LPA3588 6.1.84 #1 SMP Wed Apr 9 11:21:26 CST 2025 aarch64 aarch64 aarch64 GNU/Linux
CPU:	RK3588	APP :	-
:	LPA3588	:	100%
/ :	05	:	FD7352S
:	01	:	YT8521SC
/ :	02	EMMC :	-
:	LPA3588_ubuntu22.04_v1.0_20250415_1601.img	:	Burn In && Update
:	Ubuntu		

Description

```
eth0: flags=4163<UP,BROADCAST,RUNNING,MULTICAST> mtu 1500
    inet 192.168.1.81 netmask 255.255.255.0 broadcast 192.168.1.255
    inet6 fe80::a209:d0e9:3751:afa9 prefixlen 64 scopeid 0x20<link>
    ether e6:4b:c3:7a:fd:af txqueuelen 1000 (Ethernet)
    RX packets 781 bytes 88701 (88.7 KB)
    RX errors 0 dropped 0 overruns 0 frame 0
    TX packets 472 bytes 65016 (65.0 KB)
    TX errors 0 dropped 0 overruns 0 carrier 0 collisions 0
    device interrupt 75

eth1: flags=4099<UP,BROADCAST,MULTICAST> mtu 1500
    ether 2e:83:43:61:8d:e4 txqueuelen 1000 (Ethernet)
    RX packets 0 bytes 0 (0.0 B)
    RX errors 0 dropped 0 overruns 0 frame 0
    TX packets 0 bytes 0 (0.0 B)
    TX errors 0 dropped 0 overruns 0 carrier 0 collisions 0
    device interrupt 97 base 0xd000
```

Files

clipboard-202507021821-o2jmn.png	25.4 KB	07/02/2025	mike
----------------------------------	---------	------------	------