

Ubuntu_22.04 - Bug #1019

LPA3588_WIFI_LAN

07/02/2025 06:55 PM - mike

Status:	New	Start date:	07/02/2025
Priority:	Normal	Due date:	
Assignee:	Linx	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LP160	:	Linux LPA3588 6.1.84 #1 SMP Wed Apr 9 11:21:26 CST 2025 aarch64 aarch64 aarch64 GNU/Linux
CPU:	RK3588	APP :	-
:	LPA3588	:	100%
/ :	05	:	FD7352S
:	01	:	YT8521SC
/ :	05	EMMC :	-
:	LPA3588_ubuntu22.04_v1.0_20250415_1601.img	:	Burn In && Update
:	Ubuntu		

Description

RKDevInfoWriteTool V1.2.6

设置 日志文件 关于

SN: 0000001

WIFI: F1F2F3F4F5F6

LAN: 76C6ABB44AE57AC6ABB44AE5

BT:

IMEI:

单次读写

18:52:25 254 开始读取...

18:52:25 254 读取 SN...

18:52:25 257 读取SN:0000001成功!

18:52:25 272 读取 WIFI MAC...

18:52:25 286 读取WIFI MAC:F1F2F3F4F5F6成功!

18:52:25 299 读取 LAN MAC...

18:52:25 313 读取LAN MAC:76C6ABB44AE57AC6ABB44AE5成功!

18:52:25 325 耗时 0'110 秒

WIFI /

LAN /

Files

clipboard-202507021853-ohvwo.png	31.6 KB	07/02/2025	mike
----------------------------------	---------	------------	------