

LZ730(Hi3519 DV500) - Bug #1026

T/P J3100

07/03/2025 03:22 PM -

|                        |        |                        |                       |
|------------------------|--------|------------------------|-----------------------|
| <b>Status:</b>         | New    | <b>Start date:</b>     | 07/03/2025            |
| <b>Priority:</b>       | High   | <b>Due date:</b>       |                       |
| <b>Assignee:</b>       | sun    | <b>% Done:</b>         | 0%                    |
| <b>Category:</b>       | Driver | <b>Estimated time:</b> | 0.00 hour             |
| <b>Target version:</b> |        | <b>Spent time:</b>     | 0.00 hour             |
| <b> :</b>              |        | <b> :</b>              | busybox_V1.0-20250627 |
| <b>CPU:</b>            |        | <b> :</b>              |                       |
| <b> :</b>              |        | <b> :</b>              | Linux (none) 5.10.0   |
| <b> / :</b>            |        | <b> :</b>              |                       |
| <b> :</b>              |        | <b> :</b>              |                       |
| <b> / :</b>            | 01     | <b>EMMC :</b>          | -                     |
| <b>Description</b>     |        |                        |                       |
| T/P J3100              |        |                        |                       |