

LD180 - Bug #1075

eth0

07/17/2025 06:18 PM -

Status:	New	Start date:	07/17/2025
Priority:	High	Due date:	
Assignee:	Linx	% Done:	0%
Category:	S.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:		:	LZ180_Debian_20250710.img
CPU:		:	Ubuntu
:		:	Linux linaro-alip 6.1.118
/ :		:	
:	02	:	
/ :	01	EMMC :	-

Description

```
eth0, end0;
root@linaro-alip:/# ifconfig
end0: flags=4163<UP,BROADCAST,RUNNING,MULTICAST> mtu 1500
    inet 192.168.1.179 netmask 255.255.255.0 broadcast 192.168.1.255
    inet6 fe80::9707:e8c5:bd7e:923a prefixlen 64 scopeid 0x20<link>
    ether be:f1:df:61:9e:4f txqueuelen 1000 (Ethernet)
    RX packets 53 bytes 6932 (6.7 KiB)
    RX errors 0 dropped 0 overruns 0 frame 0
    TX packets 59 bytes 5169 (5.0 KiB)
    TX errors 0 dropped 0 overruns 0 carrier 0 collisions 0
    device interrupt 73
```

eth0

Files

clipboard-202507171817-vmfs7.png	25.1 KB	07/17/2025	
----------------------------------	---------	------------	--