

Ubuntu_22.04 - Bug #1077

LPB3568systemctl suspendUSB

07/17/2025 06:20 PM -

Status:	New	Start date:	07/17/2025
Priority:	High	Due date:	
Assignee:		% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LP120	:	Linux RK356X 6.1.99 #2 SMP Tue Apr 8 17:43:27 CST 2025 aarch64 aarch64 aarch64 GNU/Linux
CPU:	RK3568	APP:	-
:	LPB3568	:	100%
/:	05	:	FD7352S
:	04	:	YT8521SC
/:	04	EMMC:	-
:	LPB3568_ubuntu22.04_20250704_1631 	:	Button&&LED
:	Ubuntu		
Description			