

Ubuntu_22.04 - Bug #1084

LPA3588_Ubuntu22.04 USB

07/17/2025 07:13 PM - mike

Status:	New	Start date:	07/17/2025
Priority:	Normal	Due date:	
Assignee:	sun	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LP160	:	Linux LPA3588 6.1.84 #1 SMP Wed Apr 9 11:21:26 CST 2025 aarch64 aarch64 aarch64 GNU/Linux
CPU:	RK3588	APP :	-
:	LPA3588	:	100%
/ :	06	:	FD7352S
:	01	:	YT8521SC
/ :	03	EMMC :	-
:	LPA3588_ubuntu22.04_v1.0_20250415_1601.img	:	Button&&LED
:	Ubuntu	4G/5G/GPS:	
Description			
systemctl suspend			