

Ubuntu_22.04 - Bug #1090

LPA3588_Ubuntu22.04

07/18/2025 01:57 PM - mike

Status:	New	Start date:	07/18/2025
Priority:	Normal	Due date:	
Assignee:	sun	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
 :	LP160	 :	Linux LPA3588 6.1.84 #79 SMP Thu Apr 17 18:28:02 CST 2025 aarch64 aarch64 aarch64 GNU/Linux
CPU:	RK3588	APP :	-
 :	LPA3588	 :	100%
 / :	06	 :	FD7352S
 :	01	 :	YT8521SC
 / :	03	EMMC :	-
 :	LPA3588_ubuntu22.04_v1.0_20250415_1601.img	 :	Button&&LED
 :	Ubuntu	4G/5G/GPS:	
Description root@LPA3588:~# cat /sys/power/state freeze mem root@LPA3588:~#			

Files

clipboard-202507181355-wile9.png	3.13 KB	07/18/2025	mike
----------------------------------	---------	------------	------