

Ubuntu_22.04 - Bug #1104

LPA3588_Ubuntu22.04 1st Ext Hub USB2.0

07/28/2025 03:50 PM - mike

Status:	New	Start date:	07/28/2025
Priority:	Normal	Due date:	
Assignee:	sun	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LP160	:	Linux LPA3588 6.1.84 #79 SMP Thu Apr 17 18:28:02 CST 2025 aarch64 aarch64 aarch64 GNU/Linux
CPU:	RK3588	APP :	-
:	LPA3588	:	<20%
/ :	06	:	FD7352S
:	01	:	YT8521SC
/ :	03	EMMC :	-
:	LPA3588_ubuntu22.04_v1.0_20250415_1601.img	:	USB Device
:	Ubuntu	4G/5G/GPS:	RM500U 5G 4*5G M.2
Description 1.USB-A3.0 1st EXT Hub with USB2.0&3.0 2.Power off / reboot USB2.0			