

Ubuntu_22.04 - Bug #1107

LPA3588_Ubuntu22.04 8 CPU

07/31/2025 06:16 PM - mike

Status:	New	Start date:	07/31/2025
Priority:	High	Due date:	
Assignee:	sun	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LP160	:	Linux LPA3588 6.1.84 #79 SMP Thu Apr 17 18:28:02 CST 2025 aarch64 aarch64 aarch64 GNU/Linux
CPU:	RK3588	APP :	-
:	LPA3588	:	100%
/ :	06	:	FD7352S
:	01	:	YT8521SC
/ :	03	EMMC :	-
:	LPA3588_ubuntu22.04_v1.0_20250415_1601.img	:	Camera
:	Ubuntu	4G/5G/GPS:	RM500U 5G 4*5G M.2

Description

```

1 DISPLAY=:0.0 gst-launch-1.0 v4l2src device=/dev/video$i ! video/x-raw,format=NV12,width=1920,height=1080,framerate=30/1 ! fpsdisplaysink &
2 echo powersave | tee $(find /sys/ -name *governor) #
3 echo performance | tee $(find /sys/ -name *governor) #TYPE-C

```