

Ubuntu_22.04 - Bug #1114

LPA3588_Ubuntu22.04 F7352S 5G_AX80

08/06/2025 07:15 PM - mike

Status:	New	Start date:	08/06/2025
Priority:	Normal	Due date:	
Assignee:	sun	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LP160	:	Linux LPA3588 6.1.84 #79 SMP Thu Apr 17 18:28:02 CST 2025 aarch64 aarch64 aarch64 GNU/Linux
CPU:	RK3588	APP :	-
:	LPA3588	:	100%
/ :	06	:	FD7352S
:	01	:	YT8521SC
/ :	03	EMMC :	-
:	LPA3588_ubuntu22.04_v1.0_20250415_1601.img	:	BT&&WiFi
:	Ubuntu	4G/5G/GPS:	RM500U 5G 4*5G M.2

Description

```
root@LPA3588:~# iw dev wlan0 link
Connected to ec:da:59:25:cd:ec (on wlan0)
    SSID: Near_QA_Test_5G
    freq: 5200
    RX: 0 bytes (0 packets)
    TX: 0 bytes (0 packets)
    signal: 34 dBm
    rx bitrate: 648.5 MBit/s 80MHz HE-MCS 6 HE-NSS 2 HE-GI 0 HE-DCM 0
    tx bitrate: 1200.9 MBit/s 80MHz HE-MCS 11 HE-NSS 2 HE-GI 0 HE-DCM 0
root@LPA3588:~#
```

Files

clipboard-202508061914-zwnbq.png	11.2 KB	08/06/2025	mike
----------------------------------	---------	------------	------