

Ubuntu_22.04 - Bug #1116

LPA3588_Ubuntu22.04 F7352S 5G_AX20

08/06/2025 07:25 PM - mike

Status:	New	Start date:	08/06/2025
Priority:	Normal	Due date:	
Assignee:	sun	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
 :	LP160	 :	Linux LPA3588 6.1.84 #79 SMP Thu Apr 17 18:28:02 CST 2025 aarch64 aarch64 aarch64 GNU/Linux
CPU:	RK3588	APP :	-
 :	LPA3588	 :	100%
 / :	06	 :	FD7352S
 :	01	 :	YT8521SC
 / :	06	EMMC :	-
 :	LPA3588_ubuntu22.04_v1.0_20250415_1601.img	 :	BT&&WiFi
 :	Ubuntu	4G/5G/GPS:	RM500U 5G 4*5G M.2

Description

功能能极大改善无线资源效率，提升Wi-Fi体验。

无线网络模式:

a+n+ac+ax

无线网络信道频宽:

20M

Hz

TWT:

开

关

MU-MIMO:

开

关

OFDMA:

开

关

应用

```
root@LPA3588:~# iw wlan0 link
Connected to ec:da:59:25:cd:ec (on wlan0)
  SSID: Near_QA_Test_5G
  freq: 5745
  RX: 0 bytes (0 packets)
  TX: 0 bytes (0 packets)
  signal: -44 dBm
  rx bitrate: 258.0 MBit/s HE-MCS 10 HE-NSS 2 HE-GI 0 HE-DCM 0
  tx bitrate: 114.7 MBit/s HE-MCS 9 HE-NSS 1 HE-GI 0 HE-DCM 0
root@LPA3588:~#
```

Files			
clipboard-202508061924-x2fxy.png	8.17 KB	08/06/2025	mike
clipboard-202508061924-tajbe.png	10.4 KB	08/06/2025	mike