

Ubuntu_22.04 - Bug #1118

LPA3588_Ubuntu22.04 F7352S 2.4G_802.11n

08/07/2025 09:18 PM - mike

Status:	New	Start date:	08/07/2025
Priority:	Normal	Due date:	
Assignee:	sun	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LP160	:	Linux LPA3588 6.1.84 #79 SMP Thu Apr 17 18:28:02 CST 2025 aarch64 aarch64 aarch64 GNU/Linux
CPU:	RK3588	APP :	-
:	LPA3588	:	100%
/ :	06	:	FD7352S
:	01	:	YT8521SC
/ :	03	EMMC :	-
:	LPA3588_ubuntu22.04_v1.0_20250415_1601.img	:	BT&&WiFi
:	Ubuntu	4G/5G/GPS:	RM500U 5G 4*5G M.2

Description

```

root@LPA3588:~# iw dev wlan0 link
Connected to ec:da:59:25:cd:eb (on wlan0)
    SSID: Near_QA_Test
    freq: 2462
    RX: 0 bytes (0 packets)
    TX: 0 bytes (0 packets)
    signal: -25 dBm
    rx bitrate: 192.7 MBit/s VHT-MCS 9 short GI VHT-NSS 2
    tx bitrate: 96.3 MBit/s VHT-MCS 9 short GI VHT-NSS 1
root@LPA3588:~#

```

Files

clipboard-202508072117-5mokt.png	11.2 KB	08/07/2025	mike
----------------------------------	---------	------------	------