

Ubuntu 22.04 - Bug #1124

LPB3568 ☐ ☐ ☐ **NTP** ☐ ☐ ☐ ☐ ☐ ☐ **RTC** ☐ ☐ ☐ ☐ ☐

08/14/2025 12:00 PM -

Status:	New	Start date:	08/14/2025
Priority:	High	Due date:	
Assignee:	Linx	% Done:	0%
Category:	S.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Model:	LP120	Kernel:	Linux RK356X 6.1.99 #2 SMP Tue Apr 8 17:43:27 CST 2025 aarch64 aarch64 aarch64 GNU/Linux
CPU:	RK3568	APP:	-
GPU:	LPB3568 Mali-G57	Storage:	100%
RAM/Flash:	05	Storage:	FD7352S
Flash:	04	Storage:	YT8521SC
RAM/Flash:	04	EMMC:	-
Image:	LPB3568_ubuntu22.04_20250704_1631.img	Storage:	RTC
OS:	Ubuntu	4G/5G/GPS:	5G EC20 4G+GPS+1*4G+1*GPS mini-Pcie
Description			
lclipboard-202508141158-4m2fo.png			

Files

clipboard-202508141158-4m2fo.png 157 KB 08/14/2025