

LB220 - Bug #1125

3.0U 2.0

08/14/2025 04:36 PM -

Status:	New	Start date:	08/13/2025
Priority:	High	Due date:	
Assignee:		% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LB220	:	
CPU:	RK3528A	:	Debian
:		:	
/ :		:	
:		:	
/ :	01	EMMC :	-

Description

3.0U
2.0

3.0
2.0

```
root@linaro-alip:/# lsusb -t
/: Bus 02.Port 1: Dev 1, Class=root_hub, Driver=ohci-platform/1p, 12M
/: Bus 01.Port 1: Dev 1, Class=root_hub, Driver=ehci-platform/1p, 480M
   |__ Port 1: Dev 2, If 0, Class=Hub, Driver=hub/4p, 480M
       |__ Port 3: Dev 5, If 0, Class=Mass Storage, Driver=usb-storage, 480M
       |__ Port 4: Dev 3, If 4, Class=Vendor Specific Class, Driver=qmi_wwan_q, 480M
       |__ Port 4: Dev 3, If 2, Class=Vendor Specific Class, Driver=option, 480M
       |__ Port 4: Dev 3, If 0, Class=Vendor Specific Class, Driver=option, 480M
       |__ Port 4: Dev 3, If 3, Class=Vendor Specific Class, Driver=option, 480M
       |__ Port 4: Dev 3, If 1, Class=Vendor Specific Class, Driver=option, 480M
root@linaro-alip:/#
er=usb-storage, 5000M' | wc -l
0
root@linaro-alip:/#
root@linaro-alip:/# lsblk
NAME        MAJ:MIN RM  SIZE RO TYPE MOUNTPOINT
sda           8:0    1 14.3G  0 disk /media/linaro/A7
mmcblk1     179:0    0   7.2G  0 disk
├─mmcblk1p1  179:1    0    4M  0 part
├─mmcblk1p2  179:2    0    4M  0 part
├─mmcblk1p3  179:3    0   64M  0 part
├─mmcblk1p4  179:4    0  128M  0 part
├─mmcblk1p5  179:5    0   32M  0 part
├─mmcblk1p6  179:6    0  128M  0 part /oem
├─mmcblk1p7  179:7    0  128M  0 part /userdata
├─mmcblk1p8  179:8    0   6.7G  0 part /
mmcblk1boot0 179:32   0    4M  1 disk
mmcblk1boot1 179:64   0    4M  1 disk
root@linaro-alip:/#
```

Files

clipboard-202508141507-3s2tx.png	54.6 KB	08/14/2025	
----------------------------------	---------	------------	--