

LP160 - Bug #310

LPA3588_Ubuntu 20.04.5_A/I INI1 2 3 4 50mV

05/29/2023 02:44 PM -

Status:	New	Start date:	05/29/2023
Priority:	Normal	Due date:	
Assignee:	sun	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LP160	:	Ubuntu
CPU:	RK3588	:	Linux LPA3588 5.10.110
:		APP :	
/ :	02	:	
:	01	:	
/ :	03	:	
:	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	EMMC :	

Description

1 A/I INI1 2 3 4 1V 7V 14V

2

INI1----cat /sys/devices/platform/fec10000.saradc/iio\:device0/in_voltage4_raw

INI2----cat /sys/devices/platform/fec10000.saradc/iio\:device0/in_voltage2_raw

INI3----cat /sys/devices/platform/fec10000.saradc/iio\:device0/in_voltage6_raw

INI4----cat /sys/devices/platform/fec10000.saradc/iio\:device0/in_voltage7_raw

3 50mV

50mV

50mV

A/I pin2 3 4 5 1V 7V 14V

= /1024*1.8*686/82≈ (/68 (V)

History

#1 - 09/12/2023 04:45 PM -

- changed from RK3588_UBUNTU_V1_230519.img to LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img

LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img lpa3588-linux-f0