

LP160 - Bug #314

LPA3588_Ubuntu 20.04.5_RTC 00_00 timedatectl 00 00 00 00 00 00 00 00 , 00 00 00 00 00 00 00 00

05/31/2023 02:09 PM - 00

Status:	Closed	Start date:	05/31/2023
Priority:	Normal	Due date:	
Assignee:	Linx	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
ID:	LP160	OS:	Ubuntu
CPU:	RK3588	Kernel:	Linux LPA3588 5.10.110
Model:		APP:	
Board:	02	Board:	
Board:	01	Board:	
Board:	03	Board:	
Image:	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	EMMC:	

Description

000000
1000timedatectl000000000000

00000000
System clock synchronized: yes
NTP service: active
RTC in local TZ: **no**

000000
System clock synchronized: yes
NTP service: active
RTC in local TZ: **yes**

History

#1 - 06/02/2023 10:41 AM - Linx

1. RTC0000 0000 hwclock -w 0000
2. 00000000 00GU00000000

#2 - 06/02/2023 11:14 AM - sun

- Assignee changed from sun to Linx

#3 - 09/12/2023 06:18 PM - 00

- Status changed from New to Closed

- 000000 changed from RK3588_UBUNTU_V1_230519.img to LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img

0000LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img0000000000ipa3588-linux-fo00

1000000000 00GU00000000

20000000000000000000000000

In -sf /usr/share/zoneinfo/Asia/Shanghai /etc/localtime
sudo timedatectl set-timezone Asia/Shanghai