

LP162 - Bug #319

4 COM RS232

06/05/2023 06:02 PM -

Status:	New	Start date:	06/05/2023
Priority:	High	Due date:	06/13/2023
Assignee:	sun	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LP162	:	Ubuntu
CPU:	RK3588	:	Linux LPA3588 5.10.110
:		APP:	
/:	02	:	
:	01	:	
/:	03	:	
:	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	EMMC:	

Description

12345678910
12345678910232DB-9
2minicom,
DB-9

\ 1 2 3 4 5 /
\ 6 7 8 9 /

RS-232:
TXD:
RXD:

:
GND:

[17:45:08.298] U
[17:45:08.443] U
[17:45:15.141] U
[17:45:15.298] U
[17:45:15.461] U
[17:45:15.733] U
[17:48:10.227]
[17:48:10.963]
[17:48:15.232]

[RS232_1]
tty_rs232_tx_1=/dev/ttysWK0
tty_rs232_rx_1=/dev/ttysWK2
baud_rate=115200

[RS232_2]
tty_rs232_tx_2=/dev/ttysWK2
tty_rs232_rx_2=/dev/ttysWK0

```
baud_rate=115200

[RS232_3]
tty_rs232_tx_3=/dev/ttyWK1
tty_rs232_rx_3=/dev/ttyWK3
baud_rate=115200

[RS232_4]
tty_rs232_tx_4=/dev/ttyWK3
tty_rs232_rx_4=/dev/ttyWK1
baud_rate=115200
```

History

- #1 - 06/05/2023 06:03 PM -

- Subject changed from 4 COM RS232 to 4 COM RS232
- #2 - 09/18/2023 03:25 PM -

- Priority changed from Normal to High

- changed from RK3588_UBUNTU_V1_230519.img to LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img
- #3 - 09/18/2023 03:40 PM -

LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img

Files

clipboard-202306051748-uemwj.png	3.72 KB	06/05/2023	
minicom.txt	1.18 KB	06/05/2023	
com_test.sh.txt	323 Bytes	06/05/2023	
com_test.sh	764 Bytes	06/05/2023	