

LP122 - Bug #365

A/I INI1 2 3 4 50mV

06/30/2023 11:26 AM -

Status:	New	Start date:	06/30/2023
Priority:	Normal	Due date:	
Assignee:	sun	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LP122	:	Ubuntu
CPU:	RK3568	:	Linux LPA3568 4.19.232lpb3568-linux-f0dtb id 7
:		APP :	
/ :	03	:	
:	04	:	
/ :	03	:	
:	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	EMMC :	

Description

1A/I INI1 2 3 4 50mV

2

INI1----cat /sys/devices/platform/fe720000.saradc/iio\:device0/in_voltage7_raw

INI2----cat /sys/devices/platform/fe720000.saradc/iio\:device0/in_voltage6_raw

INI3----cat /sys/devices/platform/fe720000.saradc/iio\:device0/in_voltage5_raw

INI4----cat /sys/devices/platform/fe720000.saradc/iio\:device0/in_voltage4_raw

350mV

1

2INI1,IN2,IN3,IN450mv

50mV

History

#1 - 06/30/2023 05:50 PM -

- / deleted (04)
- / set to 03
- / deleted (04)
- / set to 03