

LP11A - Bug #455

MAC

05/28/2024 01:43 PM - mike

Status:	Closed	Start date:	05/28/2024
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:	Driver_[RK3568/RK3399Pro]	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LP11A	:	Ubuntu
CPU:	RK3399Pro	:	Linux bionic 4.4.194 #1 SMP Sat May 18 10:51:08 CST 2024 aarch64 aarch64 aarch64 GNU/Linux
:		APP:	-
/:	-	:	
:	03	:	
/:	02	:	
:	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V1.0\update.img	EMMC:	

Description

```
eth0: flags=4163<UP,BROADCAST,RUNNING,MULTICAST> mtu 1500
    inet 192.168.1.141 netmask 255.255.255.0 broadcast 192.168.1.255
    inet6 fe80::2c7b:acff:fe32:f111 prefixlen 64 scopeid 0x20<link>
    ether 2e:7b:ac:32:f1:11 txqueuelen 1000 (Ethernet)
    RX packets 30482 bytes 37889550 (37.8 MB)
    RX errors 0 dropped 0 overruns 0 frame 0
    TX packets 8587 bytes 2775083 (2.7 MB)
    TX errors 0 dropped 0 overruns 0 carrier 0 collisions 0
    device interrupt 24
```

History

#1 - 07/18/2024 09:47 AM -

mac uboot

#2 - 07/18/2024 09:48 AM -

#3 - 07/18/2024 03:45 PM - mike

- Status changed from New to Closed

Files

clipboard-202405281342-lqfdc.png	16.9 KB	05/28/2024	mike
----------------------------------	---------	------------	------