

LP120 - Bug #523

USB3.0 1A 500mA ±5%
<4V)

08/23/2024 04:31 PM - EGON

Status:	Closed	Start date:	08/23/2024
Priority:	High	Due date:	
Assignee:	jing	% Done:	0%
Category:	H.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
OS:	LB120	OS:	Ubuntu
CPU:	RK3568	Toolchain:	nux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #11 SMP Wed Aug 14 17:46:10 CST 2024
Board:	LPA3568M80000"	APP:	
OS/Board:	04	Build:	100%
OS/Board:	04	Build:	
OS/Board:	05	Build:	
IP:	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568	EMMC:	
Description			
USB 1A 500mA ±5% 500mA 500mA			

History

#1 - 08/23/2024 04:36 PM - mike

- Subject changed from USB 1A 500mA ±5% to USB3.0 1A 500mA ±5% <4V)

EGON wrote:

USB 1A 500mA ±5%
500mA
500mA

5W
<4V

#2 - 10/14/2024 02:37 PM - EGON

- Category changed from Driver to H.W
- Assignee changed from to jing

#3 - 10/23/2024 04:32 PM - jing

2V-5.5V, active
high, 2.1A, 70mohm, SOT23-5, TCS9263B, Torch-Chip 1.48A 0.9A TSC9163

#4 - 01/17/2025 11:28 AM - EGON

- Status changed from New to Closed