

LP120 - Bug #524

USB2.0

08/23/2024 04:47 PM - EGON

Status:	Closed	Start date:	08/23/2024
Priority:	High	Due date:	
Assignee:	jing	% Done:	0%
Category:	H.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LB120	:	Ubuntu
CPU:	RK3568	:	nux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #11 SMP Wed Aug 14 17:46:10 CST 2024
:	LPA3568M8	APP :	
/ :	04	:	100%
:	04	:	
/ :	05	:	
:	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568	EMMC :	
Description			
0.5A			
2.8V			

History

#1 - 08/23/2024 04:59 PM - EGON

J1204 4V ≈0.8A

#2 - 09/06/2024 03:51 PM - EGON

- set to Ubuntu

#3 - 10/23/2024 03:14 PM - jing

,2V-5.5V,active high,2.1A,70mohm,SOT23-5,TCS9263B,Torch-Chip1.48A0.9ATSC9163

#4 - 01/17/2025 11:28 AM - EGON

- Status changed from New to Closed