

LP120 - Bug #526

UBS3.0 □□□□□

08/26/2024 10:14 AM - EGON

Status:	Closed	Start date:	08/26/2024
Priority:	Low	Due date:	
Assignee:	□□	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
□□:	LB120	□□:	Ubuntu
CPU:	RK3568	□□□□:	Linux version 5.10.198 (yangyonghao@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #11 SMP Wed Aug 14 17:46:10 CST 2024
□□:	LPA3568M8□□□□"	APP□□:	
□□/□□□□□□□□:	04	□□□□:	<20%
□□□□□□□□:	04	□□□□:	
□□/□□□□□□□□:	05	□□□□:	
□□□□:	\\192.168.1.250\01-Public\wilson_test\rk 3568\lpa3568	EMMC□□:	
Description			
□□□ USB□□□□□□□□□□□□□□□□±%5□□□□□□□□□□□□			

History

#1 - 08/26/2024 10:16 AM - EGON

- set to \\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568
- set to Ubuntu
- set to Linux version 5.10.198 (yangyonghao@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #11 SMP Wed Aug 14 17:46:10 CST 2024
- set to <20%

#2 - 09/02/2024 02:05 PM - EGON

- Status changed from New to Closed