

LP122 - Bug #559

85°C USB

09/18/2024 03:20 PM - EGON

Status:	Closed	Start date:	09/18/2024
Priority:	Urgent	Due date:	
Assignee:	jing	% Done:	0%
Category:	H.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
ID:	LP122	OS:	Ubuntu
CPU:	RK3568	Kernel:	Linux version 4.19.232 (wangxiaocan@ubuntu2004) (gcc version 6.3.1 20170404 (Linaro GCC 6.3-2017.05), GNU ld (Linaro_Binutils-2017.05) 2.27.0.20161019) #20 SMP Thu May 23 13:50:25 CST 2024
Model:	LPM3568J	APP:	
Board:	04	Progress:	100%
Part:	04	Build:	
Version:	03	Test:	
Path:	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu\LPB3568_ubuntu20.04_HDMI_v1.0_20240524_1358	EMMC:	

Description

85°C USB

History

#1 - 09/18/2024 03:21 PM - EGON

85°C USB

#2 - 09/25/2024 09:49 AM - EGON

- Subject changed from 85°C USB to 85°C USB

#3 - 09/29/2024 06:42 PM - EGON

- Priority changed from Normal to Urgent

#4 - 10/29/2024 09:37 AM - EGON

- CPU changed from RK3568J to RK3568

#5 - 10/29/2024 09:37 AM - EGON

- Status changed from New to Closed