

LP160 - Bug #583

4pin speaker

10/29/2024 10:25 AM - EGON

Status:	New	Start date:	10/29/2024
Priority:	High	Due date:	
Assignee:	sun	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
OS:	LP160	OS:	Ubuntu
CPU:	RK3588	Kernel:	Linux version 5.10.110 (wangxiaocan@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #6 SMP Wed Sep 18 11:27:12 CST 2024
Board:	LPA3588J	APP:	Linux version 5.10.198 (yangyonghao@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #4 SMP Wed Oct 9 14:17:20 CST 2024
Test case:	05	Progress:	100%
Test result:	01	Test log:	
Test case:	03	Test log:	
Test case:	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	EMMC:	

Description
4pin speaker

History

#1 - 10/30/2024 09:58 AM - EGON

- Priority changed from Normal to High