

LP160 - Bug #585

HDMI

10/29/2024 04:50 PM - Anonymous

Status:	New	Start date:	10/29/2024
Priority:	Urgent	Due date:	
Assignee:	Linx	% Done:	0%
Category:	S.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
OS:	LP160	OS:	Ubuntu
CPU:	RK3588	OS version:	Linux version 5.10.110 (wangxiaocan@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #6 SMP Wed Sep 18 11:27:12 CST 2024
Model:	LPA3588J	APP:	Linux version 5.10.198 (yangyonghao@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #4 SMP Wed Oct 9 14:17:20 CST 2024
Test case:	05	Progress:	100%
Test case:	01	Test case:	
Test case:	03	Test case:	
Test case:	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	EMMC:	
Description			
gst sony1.mp4 HDMI			

History

- #1 - 01/14/2025 05:50 PM - Anonymous
- Subject changed from gst sony1.mp4 HDMI to HDMI
- Priority changed from Normal to Urgent