

LP160 - Bug #587

16v AHD

11/01/2024 10:02 AM - EGON

Status:	New	Start date:	11/01/2024
Priority:	Urgent	Due date:	
Assignee:	jing	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LP160	:	Ubuntu
CPU:	RK3588	:	Linux version 5.10.110 (wangxiaocan@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #6 SMP Wed Sep 18 11:27:12 CST 2024
:	LPA3588J	APP:	
/:	05	:	100%
:	01	:	
/:	03	:	
:	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	EMMC:	
Description			
12v24v16vAHD			

History

#1 - 12/27/2024 02:01 PM - EGON

- Tracker changed from Bug to Feature

#2 - 04/15/2025 03:51 PM -

16V-16.3V16.05V

#3 - 04/15/2025 05:03 PM -

- Tracker changed from Feature to Bug

- Assignee set to jing

- Priority changed from Normal to Urgent

16V-16.3V16.05V