

LPM3568 - Bug #596

USB

11/07/2024 04:07 PM - mike

Status:	Closed	Start date:	11/01/2024
Priority:	Normal	Due date:	
Assignee:	jing	% Done:	0%
Category:	H.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
OS:	LD125	OS:	Ubuntu
CPU:	RK3568B2	Kernel:	Linux version 5.10.160 (yangyonghao@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #16 SMP Tue Oct 29 15:40:39 CST 2024
Model:	LKD3568	APP:	
Board:		Progress:	100%
Version:	03	Build:	
Build:	01	Flash:	
Path:	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	EMMC:	
Description			
USB			