

LPM3568 - Bug #598

ETH1

11/07/2024 04:07 PM - mike

Status:	New	Start date:	11/04/2024
Priority:	Low	Due date:	
Assignee:		% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LD125	:	Ubuntu
CPU:	LCB3568	:	Linux version 5.10.160 (yangyonghao@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #16 SMP Tue Oct 29 15:40:39 CST 2024
:	LKD3568	APP:	
/:		:	100%
:	04	:	
/:	01	:	
:	\\192.168.1.250\01-Public\wilson_test\rk 3568\lp125\Test	EMMC:	
Description			
ETH1			

Files

17308891815706.png	19.6 KB	11/06/2024	EGON
--------------------	---------	------------	------