

LPM3568 - Bug #601

USB2.0 USB3.0

11/07/2024 04:07 PM - mike

Status:	New	Start date:	11/06/2024
Priority:	Normal	Due date:	
Assignee:	jing	% Done:	0%
Category:	H.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
 :	LD125	 :	Ubuntu
CPU:	LCB3568	 :	Linux version 5.10.160 (yangyonghao@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #16 SMP Tue Oct 29 15:40:39 CST 2024
 :	LKD3568	APP :	
 / :		 :	100%
 :	04	 :	
 / :	01	 :	
 :	\\192.168.1.250\01-Public\wilson_test\rk 3568\lp125\Test	EMMC :	
Description			
USB2.0 USB3.0			

History

#1 - 11/08/2024 11:41 AM - jing
USB SPEC