

LPM3568 - Bug #640

wlan0 wifi

11/25/2024 10:04 AM - EGON

Status:	Closed	Start date:	11/25/2024
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
 :	LD125	 :	Ubuntu
CPU:	RK3568	 :	Linux version 5.10.160 (yangyonghao@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #16 SMP Tue Oct 29 15:40:39 CST 2024
 :	LKD3568	APP :	
 / :		 :	100%
 :	03	 :	FD7352S
 / :	01	 :	
 :	\\192.168.1.250\01-Public\wilson_test\rk 3568\lp125\Test	EMMC :	-

Description

wlan0 wifi

```
root@LPA3568:/system/lib/modules# ifconfig -a
can0: flags=128<NOARP> mtu 16
    unspec 00-00-00-00-00-00-00-00-00-00-00-00-00-00-00-00 txqueuelen 10 (UNSPEC)
    RX packets 0 bytes 0 (0.0 B)
    RX errors 0 dropped 0 overruns 0 frame 0
    TX packets 0 bytes 0 (0.0 B)
    TX errors 0 dropped 0 overruns 0 carrier 0 collisions 0
    device interrupt 73

can1: flags=128<NOARP> mtu 16
    unspec 00-00-00-00-00-00-00-00-00-00-00-00-00-00-00-00 txqueuelen 10 (UNSPEC)
    RX packets 0 bytes 0 (0.0 B)
    RX errors 0 dropped 0 overruns 0 frame 0
    TX packets 0 bytes 0 (0.0 B)
    TX errors 0 dropped 0 overruns 0 carrier 0 collisions 0
    device interrupt 74

enP1p17s0: flags=4099<UP,BROADCAST,MULTICAST> mtu 1500
    ether c6:25:35:5a:22:81 txqueuelen 1000 (Ethernet)
    RX packets 0 bytes 0 (0.0 B)
    RX errors 0 dropped 0 overruns 0 frame 0
    TX packets 0 bytes 0 (0.0 B)
    TX errors 0 dropped 0 overruns 0 carrier 0 collisions 0
    device interrupt 101 base 0xd000

eth0: flags=4099<UP,BROADCAST,MULTICAST> mtu 1500
    ether 0e:bf:c5:83:e5:d0 txqueuelen 1000 (Ethernet)
    RX packets 0 bytes 0 (0.0 B)
    RX errors 0 dropped 0 overruns 0 frame 0
    TX packets 0 bytes 0 (0.0 B)
    TX errors 0 dropped 0 overruns 0 carrier 0 collisions 0
    device interrupt 47

eth2: flags=4099<UP,BROADCAST,MULTICAST> mtu 1500
    ether 0a:bf:c5:83:e5:d0 txqueuelen 1000 (Ethernet)
    RX packets 0 bytes 0 (0.0 B)
    RX errors 0 dropped 0 overruns 0 frame 0
    TX packets 0 bytes 0 (0.0 B)
    TX errors 0 dropped 0 overruns 0 carrier 0 collisions 0
    device interrupt 62

eth3: flags=4099<UP,BROADCAST,MULTICAST> mtu 1500
    ether c2:72:27:50:0a:48 txqueuelen 1000 (Ethernet)
    RX packets 0 bytes 0 (0.0 B)
    RX errors 0 dropped 0 overruns 0 frame 0
    TX packets 0 bytes 0 (0.0 B)
    TX errors 0 dropped 0 overruns 0 carrier 0 collisions 0

lo: flags=73<UP,LOOPBACK,RUNNING> mtu 65536
    inet 127.0.0.1 netmask 255.0.0.0
    inet6 ::1 prefixlen 128 scopeid 0x10<host>
    loop txqueuelen 1000 (Local Loopback)
    RX packets 1933 bytes 138341 (138.3 KB)
    RX errors 0 dropped 0 overruns 0 frame 0
    TX packets 1933 bytes 138341 (138.3 KB)
    TX errors 0 dropped 0 overruns 0 carrier 0 collisions 0
```

History

#1 - 11/25/2024 10:04 AM - EGON

- Status changed from New to Closed

#2 - 11/25/2024 10:24 AM - EGON

- changed from LP122 to LD125

Files

17321731525203.png	60.4 KB	11/25/2024	EGON
--------------------	---------	------------	------